

Field Monitoring Report
-- Pebble Exploration Project --

Personnel: William Groom (ADNR)	Inspection Date: June 16, 2014
Charlene Bringham (ADNR)	Site Contact:
Hollie Chalup (ADNR)	APMA #: 6118
<input checked="" type="checkbox"/> Inspection Type:	<input checked="" type="checkbox"/> Wildlife Observed:
<input type="checkbox"/> Complete:	<input type="checkbox"/> Bear: None
<input checked="" type="checkbox"/> Partial: Overflight	<input type="checkbox"/> Caribou: None
<input type="checkbox"/> Follow-up:	<input type="checkbox"/> Moose: None
<input type="checkbox"/> Response to Public Complaint:	<input type="checkbox"/> Waterfowl: None
	<input type="checkbox"/> Fish: None
<input checked="" type="checkbox"/> Weather Conditions:	<input type="checkbox"/> Other:
<input type="checkbox"/> Temperature: Mid 60's F	
<input type="checkbox"/> Wind: Light	<input checked="" type="checkbox"/> Water level at _____ Lake:
<input type="checkbox"/> Precipitation: Light	<input type="checkbox"/> Observed inflow:
<input type="checkbox"/> Visibility: 3-miles	<input type="checkbox"/> Observed outflow:
<input type="checkbox"/> Sky Conditions: Overcast	
<input type="checkbox"/> Ground Conditions:	
Comments: Pebble camp was overflowed by ADNR staff on the yearly overflight of mining and exploration activities of Southwest and Southcentral Alaska. No ground inspection was conducted at the time of this overflight. No active drilling was observed in the course of this overflight. Additional photos of camp, ground crew at tower structure and tundra located around Pebble region available. Photos of Pebble's Iliamna Office and core lot also available.	
Recommendations:	
Actions Needed: None	

■ Comments/General impression:



Photo 1: Pebble Camp Location on Claim block



Photo 2: Ground crew conducting work to the northwest of Pebble Camp location



Photo 3: Ground crew working on tower structure northwest of Pebble Camp.



Photo 4: Pebble Deposit to the West of Pebble Camp