

Drill Site #	Latitude (ddd.mmmm)	Longitude (-ddd.mmmm)	Datum	Associated APMA	Mining Claim ADL, BLM # or USMS	Fuel Storage (OnSite/OffSite)	Tundra Mat	Trash Containment ^[a]	Sanitary Facilities	Drill Additives	Artesian Zone	Water Discharged	Reclaimed	Plugged	Cemented	Standing Pipe	Revegetated	Date Reclaimed
9475	59.893764	-155.298561	NAD83	A20196118	ADL 516873	OnSite/Temporary	Yes	On Site	Off Site	No	Yes	No	Yes	Yes	Yes	No	Full	8/24/2020
GH08-156	59.9099	-155.4333	NAD83	A20196118	ADL 642443	OnSite/Temporary	Yes	On Site	Off Site	No	No	No	Yes	Yes	Yes	No	Full	8/24/2020

[a] All trash is contained at each drill site during operation. At completion, all debris is removed to PLP's Iliamna facility for proper disposal.