

Sump Pit #	Associated Drill Site	Latitude (ddd.mmmm)	Longitude (-ddd.mmmm)	Datum (NAD83)	Associated APMA	Mining Claim ADL, BLM # or USMS	Discharge Trench	Collection Trench Area	Pit Area (square feet)	Reclaimed	Date Reclaimed
SP-9475	9475	59.91175176	-155.2735595	NAD83	A20186118	ADL 531432	No	15	125	Yes	8/24/2020
SP-156	GH08-156	59.90996547	-155.4333002	NAD83	A20186118	ADL 642443	No	5	35	Yes	8/24/2020