

Appendix G: Cover Material Stockpile Summary

Waste Rock Cover Material Monitoring Report



Date Stockpiled	Waste Rock Type	Tonnes	Formation	Zinc_%	Stockpile Code
January 2017					
1/28/2017	Cover Material	12,430	Kayak	0.00	NOX
March 2017					
3/11/2017	Cover Material	8,719	Kayak	0.00	NOX
3/13/2017	Cover Material	4,422	Kayak	0.00	NOX
April 2017					
4/1/2017	Cover Material	12,304	Kayak	0.00	NOX
4/3/2017	Cover Material	1,698	Kayak	0.00	NOX
August 2017					
8/3/2017	Cover Material	1,012	Kayak	0.00	NOX
8/4/2017	Cover Material	776	Kayak	0.00	NOX
8/5/2017	Cover Material	1,361	Kayak	0.00	NOX
8/14/2017	Cover Material	5,383	Kayak	0.00	NOX
8/15/2017	Cover Material	10,265	Kayak	0.00	NOX
8/16/2017	Cover Material	7,388	Kayak	0.00	NOX
September 2017					
9/8/2017	Cover Material	8,295	Kayak	0.00	NOX
9/9/2017	Cover Material	5,701	Kayak	0.00	NOX
9/9/2017	Cover Material	412	Kayak	0.10	NOX
9/10/2017	Cover Material	5,191	Kayak	0.00	NOX
9/10/2017	Cover Material	368	Kayak	0.10	NOX
Total		85,725			