

Summary:

This workbook contains general information and current status of all Pebble Project boreholes inspected during 2017 and past inspection results. Information is current as of December 31, 2017.

Worksheet Organization:

<i>Pebble Boreholes_DEC 2017</i>	Summary table of general information, location data, site condition, and most recent inspection for all current Pebble Project boreholes.
<i>Field Descriptions</i>	Explanation of field content, including data limitations, if any.
<i>Borehole Notes</i>	Additional notes applicable to individual borehole records describing data limitations. Borehole records with notes are indicated by a bracketed number ('[1]', '[2]', etc.) in the relevant field.
<i>Inspection Codes</i>	Describes the alpha-numeric codes PLP assigns to each borehole upon inspection. These codes are used to characterize each location according to structural condition and maintenance/reclamation status. Codes are presented in the 'Inspection Rating' field of the summary table.

Additional Notes:

1.	Inspection records are current through December 2017. PLP does not have documented inspection records for 41 locations, primarily exploration sites from 1988/89. PLP plans to inspect these locations during the 2016 field season.
2.	The summary table contains 1357 records. However, 2 records (SRK-1 and SRK-2) are re-purposed exploration boreholes now used for monitoring. Relevant information for SRK-1 is reported under Borehole 4225; SRK-2 is reported under Borehole 4251. The SRK-1/2 sites are excluded from summary tabulations.
3.	126 boreholes were completed prior to the effective date of the Alaska Reclamation Statute (AS 27.19)--October 15, 1991.
4.	The summary table contains records for all drill sites dating back to 1988, however current inspection data is provided for only those sites currently part of the Pebble Project.

* See 'Borehole Notes' worksheet for any bracketed number ([1], [2], etc.)

** Duplicate locations indicated by grey highlight

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
0001	1988	Cominco	Exploration	199	[1]	516825	1401091.013	2160211.244	S0035035W21	8/17/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0002	1988	Cominco	Exploration	355	[1]	516825	1401103.549	2160196.474	S0035035W21	8/17/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0003	1989	Cominco	Exploration	300	[1]	516821	1401554.602	2159605.042	S0035035W21	8/17/2017	3-E					Closed [4]	Stable	Casing removed
0004	1989	Cominco	Exploration	296	[1]	516821	1401454.712	2159739.752	S0035035W21	10/1/2015	3-E					Closed [4]	Stable	
0005	1989	Cominco	Exploration	410	[1]	516825	1401114.243	2160491.261	S0035035W21	10/1/2015	3-E					Closed [4]	Stable	
0006	1989	Cominco	Exploration	356	[1]	516816	1400632.396	2158122.784	S0035035W21	8/17/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0007	1989	Cominco	Exploration	340	[1]	524787	1396231.54	2141626.191	S0045035W05	8/16/2016	3-E					Closed [4]	Stable	
0008	1989	Cominco	Exploration	301	[1]	524787	1395612.423	2141782.804	S0045035W05	8/16/2016	3-E					Closed [4]	Stable	
0009	1989	Cominco	Exploration	252	[1]	524787	1396621.194	2141599.124	S0045035W05	7/30/2017	3-D	Wood Post				Grouted and Plugged	Stable	
0010	1989	Cominco	Exploration	208	[1]	531424	1395203.821	2153164.522	S0035035W29	8/17/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0011	1989	Cominco	Exploration	426	[1]	516808	1399085.126	2156099.842	S0035035W21	8/19/2017	3-E					Closed [4]	Stable	Casing removed
0012	1989	Cominco	Exploration	366	[1]	516809	1399535.265	2156727.696	S0035035W21	8/19/2017	3-E					Closed [4]	Stable	Casing removed
0013	1989	Cominco	Exploration	427	[1]	516860	1399492.052	2152718.377	S0035035W28	8/19/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0014	1989	Cominco	Exploration	342	[1]	516854	1399689.981	2151145.446	S0035035W28	8/19/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0015	1990	Cominco	Exploration	476	[1]	516810	1402136.01	2156961.358	S0035035W21	8/19/2017	3-E					Closed [4]	Stable	Casing removed
0016	1990	Cominco	Exploration	322	[1]	516821	1401591.39	2158797.186	S0035035W21	8/19/2017	3-E					Closed [4]	Stable	Casing removed
0017	1990	Cominco	Exploration	352	[1]	516818	1403461.105	2157246.742	S0035035W21	10/4/2015	3-E					Closed [4]	Stable	
0018	1990	Cominco	Exploration	298	[1]	516815	1399431.229	2158412.514	S0035035W21	10/3/2015	3-E					Closed [4]	Stable	
0019	1990	Cominco	Exploration	448	[1]	516816	1400205.404	2157429.127	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0020	1990	Cominco	Exploration	273	[1]	516809	1400282.655	2155966.234	S0035035W21	10/5/2015	3-E					Closed [4]	Stable	
0021	1990	Cominco	Exploration	300	[1]	516810	1400971.449	2156759.141	S0035035W21	10/3/2015	3-E					Closed [4]	Stable	
0022	1990	Cominco	Exploration	865	[1]	516817	1401376.343	2157509.799	S0035035W21	10/4/2015	3-E					Closed [4]	Stable	
0023	1990	Cominco	Exploration	247	[1]	516866	1400740.466	2154334.984	S0035035W28	10/6/2015	3-E	Wood Post				Closed [4]	Stable	
0024	1990	Cominco	Exploration	209	[1]	531416	1395001.764	2150253.691	S0035035W32	9/16/2016	3-E	Wood Post				Closed [4]	Stable	
0025	1990	Cominco	Exploration	869	[1]	516817	1401613.96	2158071.799	S0035035W21	8/19/2017	3-E					Closed [4]	Stable	Casing removed
0026	1990	Cominco	Exploration	304	[1]	516822	1402605.141	2158665.116	S0035035W21	10/2/2015	3-E					Closed [4]	Stable	
0027	1990	Cominco	Exploration	309	[1]	516821	1401062.467	2158788.753	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable	
0028	1990	Cominco	Exploration	297	[1]	516873	1401334.8	2155860.409	S0035035W28	10/5/2015	3-E					Closed [4]	Stable	
0029	1990	Cominco	Exploration	311	[1]	516818	1402447.424	2157733.826	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0030	1990	Cominco	Exploration	419	[1]	516821	1402156.613	2159548.291	S0035035W21	10/2/2015	3-E					Closed [4]	Stable	
0031	1990	Cominco	Exploration	312	[1]	516822	1403254.842	2159496.098	S0035035W21	10/2/2015	3-E					Closed [4]	Stable	
0032	1990	Cominco	Exploration	313	[1]	516818	1403333.727	2158332.705	S0035035W21	10/2/2015	3-E	Wood Post				Closed [4]	Stable	
0033	1990	Cominco	Exploration	283	[1]	516811	1402830.256	2156456.359	S0035035W21	10/4/2015	3-E					Closed [4]	Stable	
0034	1990	Cominco	Exploration	263	[1]	516873	1401619.78	2154757.385	S0035035W28	10/6/2015	3-E	Wood Post				Closed [4]	Stable	
0035	1990	Cominco	Exploration	392	[1]	516821	1401394.747	2159477.057	S0035035W21	10/1/2015	3-E					Closed [4]	Stable	
0036	1990	Cominco	Exploration	828	[1]	516817	1401020.561	2157846.158	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable	
0037	1990	Cominco	Exploration	363	[1]	516819	1404301.853	2158220.545	S0035035W22	10/2/2015	3-E	Wood Post				Closed [4]	Stable	
0038	1990	Cominco	Exploration	353	[1]	516812	1404379.858	2156676.436	S0035035W22	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0039	1990	Cominco	Exploration	515	[1]	516817	1401613.004	2158073.899	S0035035W21	10/3/2015	3-E	Wood Post	8-ft Snow Pole			Closed [4]	Stable	
0040	1991	Cominco	Exploration	524	[1]	524822	1404503.127	2152703.056	S0035035W27	9/15/2017	3-D					Grouted and Plugged	Stable	
0041	1991	Cominco	Exploration	795	[1]	516817	1401422.798	2158494.996	S0035035W21	8/19/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0042	1991	Cominco	Exploration	400	[1]	524824	1403852.89	2154325.478	S0035035W27	8/19/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
0043	1991	Cominco	Exploration	323	[1]	516816	1400850.96	2158461.305	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable	
0044	1991	Cominco	Exploration	363	[1]	516871	1398419.46	2155351.692	S0035035W28	10/5/2015	3-E	Wood Post				Closed [4]	Stable	
0045	1991	Cominco	Exploration	362	[1]	516816	1400232.744	2158438.032	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable	
0046	1991	Cominco	Exploration	625	[1]	516810	1401215.754	2156400.338	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0047	1991	Cominco	Exploration	800	[1]	516816	1400434.937	2157780.766	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable	
0048	1991	Cominco	Exploration	800	[1]	516816	1400801.288	2157470.191	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0049	1991	Cominco	Exploration	698	[1]	516810	1401168.141	2157168.829	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0050	1991	Cominco	Exploration	689	[1]	516817	1401748.093	2157233.943	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0051	1991	Cominco	Exploration	650	[1]	516818	1403055.928	2158164.974	S0035035W21	9/15/2017	3-E					Closed [4]	Stable	
0052	1991	Cominco	Exploration	552	[1]	516819	1403876.586	2157590.428	S0035035W22	7/26/2016	3-E	Wood Post				Closed [4]	Stable	
0053	1991	Cominco	Exploration	574	[1]	516817	1401887.032	2157572.651	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0054	1991	Cominco	Exploration	392	[1]	516817	1402032.288	2157918.877	S0035035W21	10/3/2015	3-E					Closed [4]	Stable	
0055	1991	Cominco	Exploration	609	[1]	516817	1402098.577	2158303.533	S0035035W21	10/2/2015	3-E	Wood Post				Closed [4]	Stable	
0056	1991	Cominco	Exploration	649	[1]	516809	1400106.862	2156567.136	S0035035W21	10/3/2015	3-E					Closed [4]	Stable	
0057	1991	Cominco	Exploration	750	[1]	516822	1402931.404	2158861.452	S0035035W21	10/2/2015	3-E					Closed [4]	Stable	
0058	1991	Cominco	Exploration	500	[1]	516871	1399248.476	2155345.392	S0035035W28	10/5/2015	3-E	Wood Post				Closed [4]	Stable	
0059	1991	Cominco	Exploration	498	[1]	516827	1403902.296	2160277.638	S0035035W22	10/2/2015	3-E					Closed [4]	Stable	
0060	1991	Cominco	Exploration	400	[1]	516871	1398446.381	2155946.696	S0035035W28	10/5/2015	3-E					Closed [4]	Stable	
0061	1991	Cominco	Exploration	543	[1]	516822	1402781.119	2159558.381	S0035035W21	10/2/2015	3-E	Wood Post				Closed [4]	Stable	
0062	1991	Cominco	Exploration	625	[1]	516811	1402892.109	2157060.899	S0035035W21	10/4/2015	3-E	Wood Post				Closed [4]	Stable	
0063	1991	Cominco	Exploration	565	[1]	516821	1401815.733	2159023.07	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable	
0064	1991	Cominco	Exploration	650	[1]	516818	1402497.472	2157357.833	S0035035W21	10/4/2015	3-E					Closed [4]	Stable	
0065	1991	Cominco	Exploration	733	[1]	516818	1402356.043	2158036.645	S0035035W21	10/2/2015	3-E	Wood Post				Closed [4]	Stable	
0066	1991	Cominco	Exploration	784	[1]	516818	1403179.426	2157472.498	S0035035W21	10/4/2015	3-E					Closed [4]	Stable	
0067	1991	Cominco	Exploration	482	[1]	516822	1402525.779	2159146.031	S0035035W21	10/2/2015	3-E					Closed [4]	Stable	
0068	1991	Cominco	Exploration	534	[1]	516812	1403669.839	2155897.264	S0035035W22	7/26/2016	3-E					Closed [4]	Stable	
0069	1991	Cominco	Exploration	525	[1]	516823	1403629.591	2158982.651	S0035035W22	10/2/2015	3-E	Wood Post				Closed [4]	Stable	
0070	1991	Cominco	Exploration	337	[1]	516823	1404224.091	2159804.973	S0035035W22	10/2/2015	3-E					Closed [4]	Stable	
0071	1991	Cominco	Exploration	503	[1]	516823	1404323.368	2159102.968	S0035035W22	10/2/2015	3-E					Closed [4]	Stable	
0072	1991	Cominco	Exploration	500	[1]	516811	1402372.539	2156006.083	S0035035W21	10/5/201								

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes	
0080	1991	Cominco	Exploration	564	[1]	516809	1399894.901	2157094.445	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable		
0081	1991	Cominco	Exploration	500	[1]	516816	1399822.506	2157763.805	S0035035W21	10/3/2015	3-E	Wood Post				Closed [4]	Stable		
0082	1991	Cominco	Exploration	239	[1]	516874	1402846.495	2155258.72	S0035035W28	10/5/2015	3-E					Closed [4]	Stable		
0083	1991	Cominco	Exploration	900	[1]	516822	1402238.623	2158735.758	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0084	1991	Cominco	Exploration	650	[1]	516827	1403571.933	2160327.577	S0035035W22	8/11/2017	3-E					Closed [4]	Stable		
0085	1991	Cominco	Exploration	672	[1]	516816	1400557.896	2158082.667	S0035035W21	8/20/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed	
0086	1991	Cominco	Exploration	650	[1]	516809	1400519.275	2156271.507	S0035035W21	8/20/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed	
0087	1991	Cominco	Exploration	668	[2]	516816	1400851.058	2158460.546	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0088	1992	Cominco	Exploration	403	[2]	516816	1400603.372	2157747.347	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0089	1992	Cominco	Exploration	400	[2]	516817	1401026.307	2157455.731	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0090	1992	Cominco	Exploration	404	[2]	516817	1400878.732	2158169.411	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0091	1992	Cominco	Exploration	400	[2]	516817	1401311.386	2157857.984	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0092	1992	Cominco	Exploration	400	[2]	516817	1401193.159	2158548.997	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0093	1992	Cominco	Exploration	400	[2]	516817	1401604.214	2158266.068	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0094	1992	Cominco	Exploration	400	[2]	516816	1400320.407	2157302.114	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0095	1992	Cominco	Exploration	400	[2]	516809	1400723.891	2157029.354	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0096	1992	Cominco	Exploration	400	[2]	516809	1400049.235	2156908.159	S0035035W21	8/11/2017	3-E	Wood Post				Closed [4]	Stable		
0097	1992	Cominco	Exploration	402	[2]	516809	1400452.275	2156622.776	S0035035W21	8/11/2017	3-E					Closed [4]	Stable		
0098	1992	Cominco	Exploration	700	[2]	516816	1400444.655	2158158.816	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed	
0099	1992	Cominco	Exploration	700	[2]	516817	1400950.38	2157804.529	S0035035W21	9/16/2017	3-E					Closed [4]	Stable	Casing removed	
0100	1992	Cominco	Exploration	700	[2]	516817	1401366.301	2157503.079	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed	
0101	1992	Cominco	Exploration	500	[2]	516816	1400106.325	2157741.974	S0035035W21	8/11/2017	3-E					Closed [4]	Stable		
0102	1993	Cominco	Exploration	313	1993	516957	1399041.482	2139904.108	S0045035W09	9/16/2016	3-E					Closed [4]	Stable		
0103	1993	Cominco	Exploration	303	1993	516954	1398420.501	2138526.556	S0045035W09	9/17/2017	3-E	Wood Post				Closed [4]	Stable		
0104	1993	Cominco	Exploration	324	1993	516959	1400859.528	2139532.894	S0045035W09	8/16/2016	3-E	Wood Post				Closed [4]	Stable		
0105	1993	Cominco	Exploration	323	1993	516967	1400874.737	2141469.321	S0045035W04	8/16/2016	3-E	Wood Post				Closed [4]	Stable		
0106	1997	Cominco	Exploration	1203	1997	516823	1403940.246	2158627.194	S0035035W22	8/11/2017	3-E		8-ft Snow Pole			Bentonite plug [6]	Stable		
0107	1997	Cominco	Exploration	800	1997	540400	1404863.785	2159087.859	S0035035W22	8/11/2017	3-E	Wood Post				Bentonite plug [6]	Stable		
0108	1997	Cominco	Exploration	800	1997	540401	1404909.596	2160871.974	S0035035W22	8/11/2017	3-E					Bentonite plug [6]	Stable		
0109	1997	Cominco	Exploration	793	1997	516826	1402731.681	2160809.707	S0035035W21	8/11/2017	3-E					Bentonite plug [6]	Stable		
0110	1997	Cominco	Exploration	800	1997	540399	1404936.828	2157532.689	S0035035W22	8/11/2017	3-E					Bentonite plug [6]	Stable		
0111	1997	Cominco	Exploration	213	1997	516830	1404589.854	2161881.116	S0035035W15	8/15/2016	3-E					Bentonite plug [6]	Stable		
0112	1997	Cominco	Exploration	500	1997	516873	1401954.071	2155383.252	S0035035W28	9/15/2017	3-E					Bentonite plug [6]	Stable		
0113	1997	Cominco	Exploration	1253	1997	516818	1402847.334	2158187.094	S0035035W21	8/11/2017	3-E		8-ft Snow Pole			Bentonite plug [6]	Stable		
0114	1997	Cominco	Exploration	500	1997	516872	1400466.192	2155040.213	S0035035W28	8/11/2017	3-E	Wood Post				Bentonite plug [6]	Stable		
0115	1997	Cominco	Exploration	500	1997	524826	1403982.585	2154815.26	S0035035W27	8/11/2017	3-E					Bentonite plug [6]	Stable		
0116	1997	Cominco	Exploration	989.5	1997	540400	1405892.673	2159680.882	S0035035W22	8/11/2017	3-E					Bentonite plug [6]	Stable		
0117	1997	Cominco	Exploration	1193	1997	516809	1400841.026	2156852.968	S0035035W21	8/11/2017	3-E					Bentonite plug [6]	Stable		
0118	1997	Cominco	Exploration	1500	1997	516817	1401612.443	2157373.104	S0035035W21	8/11/2017	3-E					Bentonite plug [6]	Stable		
0119	1997	Cominco	Exploration	500	1997	516825	1401655.794	2160673.153	S0035035W21	7/28/2017	3-E					Closed [4]	Stable	Casing removed	
0120	1997	Cominco	Exploration	500	1997	516821	1401001.203	2159672.898	S0035035W21	8/11/2017	3-E					Bentonite plug [6]	Stable		
0121	1997	Cominco	Exploration	500	1997	516813	1395793.181	2157821.101	S0035035W20	9/16/2016	3-E					Bentonite plug [6]	Stable		
0122	1997	Cominco	Exploration	500	1997	516814	1397163.251	2157560.649	S0035035W20	7/26/2016	3-E	Wood Post				Bentonite plug [6]	Stable		
0123	1997	Cominco	Exploration	700	1997	540401	1405297.511	2160825.023	S0035035W22	9/16/2017	3-E					Closed [4]	Stable	Casing removed	
0124	1997	Cominco	Exploration	251	1997	516827	1404500.719	2160896.203	S0035035W22	9/16/2017	3-E					Closed [4]	Stable	Casing removed	
0125	1997	Cominco	Exploration	700	1997	540401	1405195.318	2160926.32	S0035035W22	9/16/2017	1-E	Casing	8-ft Snow Pole	Steel casing/Plug or Cap	18	Closed [4]	Stable	Reclassified as active site	
2001	2002	NDM	Exploration	301	2002	516870	1397124.012	2155262.076	S0035035W29	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2002	2002	NDM	Exploration	210	2002	524812	1398444.217	2148990.411	S0035035W33	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable		
2003	2002	NDM	Exploration	470	2002	516864	1398008.698	2154285.836	S0035035W29	8/11/2017	3-E	Wood Post			8-ft Snow Pole	Grouted and Plugged [7]	Stable		
2004	2002	NDM	Exploration	500	2002	524801	1397269.503	2146726.096	S0035035W32	9/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable		
2005	2002	NDM	Exploration	500	2002	531411	1393808.512	2148773.332	S0035035W32	9/16/2017	3-E					Closed [4]	Stable	Casing removed	
2006	2002	NDM	Exploration	120	2002	531424	1395085.975	2152692.997	S0035035W29	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2007	2002	NDM	Exploration	400	2002	531424	1395086.034	2152692.79	S0035035W29	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2008	2002	NDM	Exploration	390	2002	531406	1392623.765	2147961.935	S0035035W31	9/16/2016	3-E					Closed [4]	Stable		
2009	2002	NDM	Exploration	200	2002	516851	1395967.319	2151165.297	S0035035W29	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2010	2002	NDM	Exploration	500	2002	531416	1395383.253	2149903.78	S0035035W32	9/17/2017	3-E					Closed [4]	Stable	Casing removed	
2011	2002	NDM	Exploration	380	2002	524811	1396805.022	2148246.327	S0035035W32	9/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable		
2012	2002	NDM	Exploration	498	2002	524791	1397419.763	2143247.771	S0045035W05	9/16/2016	3-E					Grouted and Plugged [7]	Stable		
2013	2002	NDM	Exploration	341	2002	516852	1397458.888	2151074.981	S0035035W29	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable		
2014	2002	NDM	Exploration	500	2002	524792	1398999.105	2143960.777	S0045035W04	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable		
2015	2002	NDM	Exploration	446	2002	516858	1397095.975	2152845.604	S0035035W29	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2016	2002	NDM	Exploration	490	2002	516843	1401790.283	2146855.553	S0035035W33	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable		
2017	2002	NDM	Exploration	500	2002	524807	1399081.624	2146828.356	S0035035W33	9/16/2016	3-E					Grouted and Plugged [7]	Stable		
2018	2002	NDM	Exploration	810	2002	516861	1401436.786	2152822.576	S0035035W28	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2019	2002	NDM	Exploration	440	2002	516849	1400956.342	2149858.663	S0035035W33	9/16/2016	3-E					8-ft Snow Pole	Grouted and Plugged [7]	Stable	
2020	2002	NDM	Exploration	440	2002	516855	1402061.076	2151193.5	S0035035W28	9/16/2016	3-E					Grouted and Plugged [7]	Stable		
2021	2002	NDM	Exploration	348	2002	516840	1401337.73	2145994.085	S0035035W33	9/16/2016	3-E					Grouted and Plugged [7]	Stable		
2022	2002	NDM	Exploration	410	2002	531432	1395532.847	2155475.084	S0035035W29	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2023	2002	NDM	Exploration	360	2002	516965	1398517.171	2141467.952	S0045035W04	8/16/2016	3-E					Grouted and Plugged [7]	Stable		
2024	2002	NDM	Exploration	185	2002	524829	1396452.883	2159481.714	S0035035W20	8/16/2016	3-E				8-ft Snow Pole	Grouted and Plugged [7]	Stable		
2025	2002	NDM	Exploration	360	2002	524784	1396071.539	2140615.486	S0045035W05	8/16/2016									

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
2038	2002	NDM	Exploration	1180	2002	638800	1378107.183	2122955.309	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2039	2002	NDM	Exploration	320	2002	516862	1402876.667	2152701.656	S0035035W28	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
2040	2002	NDM	Exploration	470	2002	516844	1403188.502	2146741.27	S0035035W33	9/16/2016	3-E					Grouted and Plugged [7]	Stable	
2041	2002	NDM	Exploration	330	2002	566638	1384225	2123527.819	S0045036W25	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
2042	2002	NDM	Exploration	560	2002	638816	1378467.665	2121648.043	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2043	2002	NDM	Exploration	630	2002	638816	1377154.827	2121649.596	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2044	2002	NDM	Exploration	861	2002	638800	1378036.41	2122935.555	S0045036W26	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
2045	2002	NDM	Exploration	906	2002	638800	1378178.399	2122972.803	S0045036W26	7/20/2017	3-E					Grouted and Plugged [7]	Stable	
2046	2002	NDM	Exploration	600	2002	638800	1378767.13	2122965.529	S0045036W26	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
2047	2002	NDM	Exploration	826	2002	638800	1376803.842	2122926.847	S0045036W26	8/16/2016	3-E					Grouted and Plugged [7]	Stable	
2048	2002	NDM	Exploration	830	2002	638800	1378091.79	2123937.186	S0045036W26	9/15/2017	3-E					Grouted and Plugged [7]	Stable	Casing removed
2049	2002	NDM	Exploration	926	2002	638800	1378106.238	2122622.529	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2050	2002	NDM	Exploration	750	2002	638785	1378742.105	2124745.266	S0045036W23	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2051	2002	NDM	Exploration	327	2002	638816	1376788.434	2120330.588	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2052	2002	NDM	Exploration	636	2002	638794	1361863.814	2123526.903	S0045036W29	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
2053	2002	NDM	Exploration	610	2002	638824	1361815.237	2118279.968	S0045036W32	9/15/2017	3-E					Grouted and Plugged [7]	Stable	Casing removed
2054	2002	NDM	Exploration	616	2002	638795	1363502.799	2123510.481	S0045036W29	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
2055	2002	NDM	Exploration	700	2002	638823	1359717.821	2118601.676	S0045036W31	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2056	2002	NDM	Exploration	696	2002	531394	1394880.448	2141785.465	S0045035W05	8/16/2016	3-E					Grouted and Plugged [7]	Stable	
2057	2002	NDM	Exploration	690	2002	638824	1361646.731	2118922.382	S0045036W32	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2058	2002	NDM	Exploration	736	2002	524784	1396052.255	2141270.996	S0045035W05	8/16/2016	3-E					Grouted and Plugged [7]	Stable	
2059	2002	NDM	Exploration	650	2002	524815	1395920.368	2149901.613	S0035035W32	9/17/2017	3-E					Grouted and Plugged [7]	Stable	Casing removed
2060	2002	NDM	Exploration	656	2002	524784	1396355.196	2140981.355	S0045035W05	9/15/2017	3-E					Closed [4]	Stable	Casing removed
2061	2002	NDM	Exploration	600	2002	531416	1395399.976	2150302.468	S0035035W32	9/16/2016	3-E					Grouted and Plugged [7]	Stable	
2062	2002	NDM	Exploration	706	2002	524787	1396383.792	2142007.312	S0045035W05	9/16/2016	3-E					Grouted and Plugged [7]	Stable	
2063	2002	NDM	Exploration	980	2002	638800	1378426.669	2123863.712	S0045036W26	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
2064	2002	NDM	Exploration	1156	2002	638800	1378436.295	2122791.982	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2065	2002	NDM	Exploration	1000	2002	638800	1377436.252	2123851.332	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2066	2002	NDM	Exploration	576	2002	638794	1362508.604	2123615.381	S0045036W29	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2067	2002	NDM	Exploration	980	2002	638800	1377447.463	2122793.862	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
2068	2002	NDM	Exploration	496	2002	638794	1362145.354	2124703.376	S0045036W29	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
3069	2003	NDM	Exploration	1156	2003	524828	1404929.132	2157101.114	S0035035W22	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3070	2003	NDM	Exploration	724	2003	516822	1402722.941	2159178.8	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
3071	2003	NDM	Exploration	729	2003	516817	1401121.452	2158228.529	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3072	2003	NDM	Exploration	747	2003	516818	1403067.327	2158159.614	S0035035W21	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3073	2003	NDM	Exploration	855	2003	531416	1394130.701	2149551.18	S0035035W32	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
3074	2003	NDM	Exploration	710	2003	540402	1405025.779	2162038.224	S0035035W15	7/20/2017	3-E					Grouted and Plugged [7]	Stable	
3075	2003	NDM	Exploration	758	2003	531411	1393073.758	2148898.836	S0035035W32	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3076	2003	NDM	Exploration	1166	2003	524828	1405229.34	2157028.205	S0035035W22	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3077	2003	NDM	Exploration	491	2003	531403	1393917.744	2145923.115	S0035035W32	9/16/2016	3-E					Grouted and Plugged [7]	Stable	
3078	2003	NDM	Exploration	731	2003	516823	1404304.922	2159234.376	S0035035W22	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3079	2003	NDM	Exploration	599	2003	516823	1403813.216	2159193.21	S0035035W22	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3080	2003	NDM	Exploration	889	2003	516819	1404542.727	2157414.597	S0035035W22	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3081	2003	NDM	Exploration	490	2003	516822	1403249.525	2158947.572	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3082	2003	NDM	Exploration	1329	2003	516810	1401029.13	2156980.429	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3083	2003	NDM	Exploration	759	2003	516822	1403254.144	2158517.598	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3084	2003	NDM	Exploration	989	2003	516821	1401747.072	2158634.707	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3085	2003	NDM	Exploration	1548	2003	516821	1401492.6	2157734.096	S0035035W21	7/23/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3086	2003	NDM	Exploration	1338	2003	516810	1401407.351	2156806.788	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3087	2003	NDM	Exploration	1159	2003	516810	1402039.237	2156631.301	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3088	2003	NDM	Exploration	660	2003	638824	1362351.489	2119324.342	S0045036W32	7/20/2017	3-E					Closed [4]	Stable	Casing removed
3089	2003	NDM	Exploration	1159	2003	516817	1401777.616	2157479.81	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3090	2003	NDM	Exploration	655	2003	638824	1362631.619	2119096.604	S0045036W32	9/15/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3091	2003	NDM	Exploration	807	2003	638800	1376826.038	2122650.476	S0045036W26	7/25/2016	3-C					Closed [4]	Stable	Re-inspect in 2018 to verify site condition
3092	2003	NDM	Exploration	1036	2003	516821	1401578.884	2158553.746	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3093	2003	NDM	Exploration	567	2003	516817	1401966.625	2158208.077	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3094	2003	NDM	Exploration	1318	2003	516810	1401753.761	2156685.327	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3095	2003	NDM	Exploration	1408.5	2003	516817	1401005.236	2157501.326	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3096	2003	NDM	Exploration	1843	2003	516810	1401700.199	2156279.651	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3097	2003	NDM	Exploration	367	2003	516816	1400614.68	2157456.956	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3098	2003	NDM	Exploration	1228	2003	516809	1400484.798	2156961.926	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3099	2003	NDM	Exploration	1354	2003	516818	1402260.291	2157257.995	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3100	2003	NDM	Exploration	116	2003	516809	1400486.176	2156961.081	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3101	2003	NDM	Exploration	1242.6	2003	516809	1400740.478	2156386.32	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3102	2003	NDM	Exploration	1258	2003	516811	1402556.873	2156782.688	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3103	2003	NDM	Exploration	908	2003	516825	1400972.645	2160610.747	S0035035W21	9/16/2017	3-E					Closed [4]	Stable	Casing removed
3104	2003	NDM	Exploration	1478	2003	516821	1401390.552	2158798.947	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3105	2003	NDM	Exploration	1438	2003	516816	1399566.384	2157601.926	S0035035W21	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3106	2003	NDM	Exploration	1378	2003	516821	1402107.268	2158562.487	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3107	2003	NDM	Exploration	809	2003	540403	1405423.521	2163671.085	S0035035W15	8/15/2016	3-E							

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
3125	2003	NDM	Exploration	1119	2004	516827	1404586.887	2160230.349	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3126	2003	NDM	Exploration	1318	2004	540400	1404938.468	2159584.22	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3127	2003	NDM	Exploration	1318	2004	516873	1401960.748	2155401.824	S0035035W28	9/15/2017	1-B	Wood Post		Steel Casing	3	Grouted and Plugged [7]	Stable	
3128	2003	NDM	Exploration	1598	2004	516811	1402340.576	2156194.003	S0035035W21	10/3/2017	3-E	Wood Post				Closed [4]	Stable	Additional repairs in 2018
3129	2003	NDM	Exploration	1320	2004	540400	1405208.488	2158605.214	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
3130	2003	NDM	Exploration	1318	2004	516812	1404061.031	2156082.736	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
3131	2003	NDM	Exploration	140	2004	516873	1401852.352	2155343.151	S0035035W28	9/15/2017	3-E	Wood Post				Closed [4]	Stable	
3132	2003	NDM	Exploration	180	2004	516873	1401852.173	2155343.275	S0035035W28	9/15/2017	3-D					Grouted and Plugged [7]	Stable; additional reclamation in 2018	Grouted and plugged in 2017 (repairs)
3133	2003	NDM	Exploration	1348	2004	516867	1402105.379	2154557.498	S0035035W28	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Water Valve	24	Grouted and Plugged [7]	Stable	
3134	2003	NDM	Exploration	1218	2004	516874	1403220.275	2155531.673	S0035035W28	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
3135	2003	NDM	Exploration	1338	2004	516868	1402710.552	2154458.581	S0035035W28	9/16/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed
4136	2004	NDM	Exploration	1140	2004	524828	1405935.544	2156357.877	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4137	2004	NDM	Exploration	1252	2004	524828	1405315.255	2156796.358	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4138	2004	NDM	Exploration	1124	2004	516811	1403207.78	2156102.841	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4139	2004	NDM	Exploration	508	2004	516817	1401210.138	2157679.553	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4140	2004	NDM	Exploration	657	2004	516811	1403452.136	2156870.264	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4141	2004	NDM	Exploration	1129	2004	524826	1403845.033	2155448.328	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4142	2004	NDM	Exploration	929	2004	516817	1401211.465	2157686.329	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4143	2004	NDM	Exploration	889	2004	516817	1401444.5	2157253.205	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4144	2004	NDM	Exploration	959	2004	516812	1404685.151	2156926.519	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4145	2004	NDM	Exploration	919	2004	516810	1401863.561	2157036.228	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4146	2004	NDM	Exploration	488	2004	516810	1401937.241	2156362.702	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4147	2004	NDM	Exploration	699	2004	516810	1401594.784	2156993.528	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4148	2004	NDM	Exploration	699	2004	516810	1402113.508	2156593.491	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4149	2004	NDM	Exploration	1553	2004	540399	1405306.264	2157298.293	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4150	2004	NDM	Exploration	869	2004	516810	1401729.538	2156746.355	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4151	2004	NDM	Exploration	369	2004	516810	1401443.435	2156244.146	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4152	2004	NDM	Exploration	459	2004	516810	1401684.863	2156293.86	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4153	2004	NDM	Exploration	948	2004	516810	1401549.587	2156529.772	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4154	2004	NDM	Exploration	949	2005	524828	1404949.221	2156500.303	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4155	2004	NDM	Exploration	1019	2004	524828	1405392.716	2156236.243	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4156	2004	NDM	Exploration	979	2004	524827	1404884.793	2156610.198	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4157	2004	NDM	Exploration	579	2004	524828	1404845.115	2156090.771	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4158	2004	NDM	Exploration	1039	2004	516874	1403326.074	2155333.093	S0035035W28	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4159	2004	NDM	Exploration	497	2004	516812	1403874.957	2155879.263	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4160	2004	NDM	Exploration	1079	2004	516826	1403444.312	2160167.386	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4161	2004	NDM	Exploration	719	2004	816874	1402690.204	2155523.676	S0035035W28	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4162	2004	NDM	Exploration	709	2004	516873	1402017.539	2155718.539	S0035035W28	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4163	2004	NDM	Exploration	698	2004	516827	1404193.135	2159914.669	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4164	2004	NDM	Exploration	1029	2004	516873	1401029.583	2155445.729	S0035035W28	9/16/2017	3-D					Grouted and Plugged [7]	Stable	
4165	2004	NDM	Exploration	1285	2004	516873	1402123.147	2155502.087	S0035035W28	9/15/2017	1-E	Wood Post	8-ft Snow Pole	Steel casing/Plug or Cap	24	Grouted and Plugged [7]	Stable	
4166	2004	NDM	Exploration	1081	2004	816823	1403729.043	2159751.552	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4167	2004	NDM	Exploration	979	2004	516872	1400794.979	2155872.66	S0035035W28	9/16/2017	3-E					Grouted and Plugged [7]	Stable	
4168	2004	NDM	Exploration	980	2004	516822	1403165.566	2159722.286	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4169	2004	NDM	Exploration	869	2004	516812	1403771.959	2156691.231	S0035035W22	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4170	2004	NDM	Exploration	529	2004	516822	1403417.382	2159288.864	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4171	2004	NDM	Monitoring/Study	1039	2004	516812	1404404.107	2155930.671	S0035035W22	9/16/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	2	Grouted and Plugged [7]	Stable	
4172	2004	NDM	Monitoring/Study	951	2004	516823	1403968.358	2159322.282	S0035035W22	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	12	Grouted and Plugged [7]	Stable	
4173	2004	NDM	Exploration	951	2004	516823	1404531.42	2159307.569	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4174	2004	NDM	Exploration	279	2004	516823	1404254.652	2158768.116	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4175	2004	NDM	Exploration	1598	2004	516809	1400609.844	2156867.866	S0035035W21	9/16/2017	3-E					Grouted and Plugged [7]	Stable	Casing removed
4176	2004	NDM	Exploration	979	2004	516812	1404688.549	2156345.6	S0035035W22	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4177	2004	NDM	Exploration	1149	2004	516823	1404254.652	2158768.116	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4178	2004	NDM	Exploration	1083	2004	516822	1403430.096	2158742.317	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4179	2004	NDM	Exploration	309	2004	516810	1401057.362	2156317.049	S0035035W21	9/16/2017	1-D	Wood Post		Steel casing/Plug or Cap	0	Grouted and Plugged [7]	Stable	
4180	2004	NDM	Exploration	709	2004	516810	1401244.656	2156545.208	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4181	2004	NDM	Monitoring/Study	1115	2004	540399	1404944.605	2158376.645	S0035035W22	8/11/2017	1-E	Wood Post		Steel Casing/Monument	2	Grouted and Plugged [7]	Stable	
4182	2004	NDM	Exploration	1008	2004	516810	1401065.907	2156837.46	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4183	2004	NDM	Exploration	819	2004	516827	1403835.798	2160771.701	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4184	2004	NDM	Exploration	718	2004	516809	1400765.254	2156863.822	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4185	2004	NDM	Exploration	589	2004	516822	1403397.81	2159273.355	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4186	2004	NDM	Exploration	498	2004	516816	1400841.752	2157254.373	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4187	2004	NDM	Exploration	560	2004	516809	1400323.993	2157116.063	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4188	2004	NDM	Exploration	1504	2004	542567	1406143.465	2156872.664	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4189	2004	NDM	Exploration	974	2004	516811	1402319.217	2156756.486	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4190	2004	NDM	Exploration	479	2004	516811	1402453.587	2156529.157	S0035035W21	7/30/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable	
4191	2004	NDM	Exploration	499	2004	516811	1402682.79	2156644.798	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4192	2004	NDM	Exploration	409	2004	516811	1403133.4	2156898.967	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4193	2004	NDM	Exploration	469	2004	516811	1402956.345	2156711.956	S0035035W21	8/11								

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
4211	2004	NDM	Exploration	579	2004	516811	1402812.168	2156928.738	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4212	2004	NDM	Exploration	559	2004	516811	1403269.156	2156664.989	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4213	2004	NDM	Exploration	529	2004	516811	1403329.282	2157096.113	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4214	2004	NDM	Exploration	1019	2004	516818	1403069.681	2157554.11	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4215	2004	NDM	Exploration	649	2004	516818	1403204.003	2157298.936	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4216	2004	NDM	Exploration	939	2004	516818	1402976.818	2157770.327	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4217	2004	NDM	Exploration	889	2004	516818	1402334.46	2157834.561	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4218	2004	NDM	Exploration	774	2004	516811	1402501.555	2157098.324	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4219	2004	NDM	Exploration	989	2004	516817	1402154.07	2157583.821	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4220	2004	NDM	Exploration	909	2004	516817	1400983.693	2157587.316	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4221	2004	NDM	Exploration	858	2004	516817	1401324.046	2158014.53	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4222	2004	NDM	Monitoring/Study	739	2004	516816	1400690.431	2157583.22	S0035035W21	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	3			Casing removed
4223	2004	NDM	Exploration	578	2004	516809	1400522.772	2156722.281	S0035035W21	9/15/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable	
4224	2004	NDM	Monitoring/Study	169	2005	516829	1403452.001	2161276.502	S0035035W16	9/16/2017	3-E					Grouted and Plugged [7]	Stable	
4225	2004	NDM	Monitoring/Study	410	2004	516829	1403453.446	2161277.084	S0035035W16	9/16/2017	1-E	Wood Post		Steel Casing	4			
4226	2004	NDM	Exploration	899	2004	516818	1402670.68	2158268.898	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4227	2004	NDM	Exploration	276.5	2004	516818	1402448.268	2157597.053	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4228	2004	NDM	Exploration	111	2004	516818	1402448.082	2157596.579	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4229	2004	NDM	Exploration	919	2004	516818	1402378.3	2158274.916	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4230	2004	NDM	Exploration	1018	2004	516818	1402436.123	2157578.563	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4231	2004	NDM	Exploration	809	2004	516818	1402747.229	2157604.474	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4232	2004	NDM	Exploration	919	2004	516810	1402099.276	2157175.965	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4233	2004	NDM	Exploration	859	2004	516818	1402547.576	2157973.086	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4234	2004	NDM	Exploration	909	2005	516818	1402539.982	2158503.1	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4235	2004	NDM	Monitoring/Study	699	2004	516822	1402419.948	2159036.191	S0035035W21	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	16			
4236	2004	NDM	Exploration	819	2004	516818	1402858.711	2158487.004	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4237	2004	NDM	Exploration	349	2004	516818	1403453.714	2158180.55	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4238	2004	NDM	Exploration	889	2004	516818	1403220.328	2157807.329	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4239	2004	NDM	Exploration	509	2004	516812	1403593.718	2157159.296	S0035035W22	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4240	2004	NDM	Exploration	479	2004	516818	1402821.806	2157991.278	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4241	2004	NDM	Exploration	389	2005	513821	1401790.769	2159317.925	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4242	2004	NDM	Exploration	699	2004	516821	1401039.649	2159083.416	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4243	2004	NDM	Exploration	439	2005	516821	1401290.181	2159149.3	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4244	2004	NDM	Monitoring/Study	599	2004	516816	1401231.612	2158728.825	S0035035W21	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	9			
4245	2004	NDM	Exploration	379	2004	516825	1400580.035	2158307.033	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4246	2004	NDM	Exploration	659	2004	516820	1402028.347	2160016.205	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4247	2004	NDM	Exploration	549	2004	516808	1400397.36	2159195.704	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4248	2004	NDM	Exploration	659	2004	516872	1398906.81	2156252.36	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4249	2004	NDM	Exploration	599	2004	540424	1400243.589	2154691.748	S0035035W28	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4250	2004	NDM	Monitoring/Study	998	2004	542569	1406852.664	2158116.05	S0035035W22	8/11/2017	1-E	Wood Post		Steel Casing/Monument	6			
4251	2004	NDM	Monitoring/Study	2008	2005	516820	1406267.338	2159570.819	S0035035W22	8/11/2017	1-E	Wood Post		Steel Casing/Monument	4			
4252	2004	NDM	Exploration	509	2004	516821	1400686.743	2158611.982	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4253	2004	NDM	Exploration	419	2004	516819	1401644.407	2159145.996	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4254	2004	NDM	Exploration	559	2004	516812	1404170.911	2157743.391	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4255	2004	NDM	Exploration	559	2004	516819	1404536.474	2157084.985	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4256	2004	NDM	Exploration	905	2004	516819	1403986.29	2157525.065	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4257	2004	NDM	Exploration	529	2004	516819	1403743.101	2157974.41	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4258	2004	NDM	Exploration	459	2004	516819	1404285.344	2157528.555	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4259	2004	NDM	Exploration	909	2004	516819	1403872.171	2157751.727	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4260	2004	NDM	Exploration	509	2004	516819	1404417.595	2157312.338	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4261	2004	NDM	Exploration	639	2004	516819	1403589.959	2157435.559	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4262	2004	NDM	Exploration	765	2004	516819	1404121.282	2157288.679	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4263M	2004	NDM	Exploration	660	2004	516816	1400564.831	2157272.053	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4264M	2004	NDM	Exploration	135	2004	516817	1401030.292	2158027.053	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4265M	2004	NDM	Exploration	664	2004	516817	1401701.766	2157844.649	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4266M	2004	NDM	Exploration	679	2004	516817	1401983.575	2157373.204	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4267M	2004	NDM	Exploration	665	2004	516817	1401034.405	2158557.809	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4268M	2004	NDM	Monitoring/Study	422	2004	516810	1400933.572	2156549.622	S0035035W21	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	2			
4269M	2004	NDM	Monitoring/Study	664	2004	516818	1402886.036	2157357.337	S0035035W21	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	6			
4270M	2004	NDM	Monitoring/Study	805	2004	516817	1401054.417	2157430.596	S0035035W21	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	12			
4271M	2004	NDM	Exploration	665	2004	516821	1401576.663	2158689.242	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4272	2004	NDM	Monitoring/Study	619	2004	516867	1401959.213	2154291.883	S0035035W28	8/11/2017	1-E	Wood Post				Grouted and Plugged [7]	Stable	
4273	2004	NDM	Exploration	999	2004	516815	1398281.064	2157313.953	S0035035W21	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4274	2004	NDM	Exploration	999	2004	516861	1400988.32	2153177.927	S0035035W28	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4275M	2004	NDM	Exploration	1005	2004	516819	1403595.851	2157703.874	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4276M	2004	NDM	Exploration	1080	2004	516818	1403237.246	2158094.385	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4277M	2004	NDM	Exploration	956	2004	516811	1402217.841	2156413.753	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4278M	2004	NDM	Exploration	959	2004	516812	1403977.634	2157005.263	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4279	2004	NDM	Exploration	629	2004	516818	1403396.805	2157622.204	S0035035W21	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4280	2004	NDM	Exploration	859	2004	516819												

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
4295M	2004	NDM	Exploration	860	2005	516816	1400876.201	2158182.681	S0035035W21	7/24/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4296M	2004	NDM	Exploration	990	2005	516821	1401041.861	2158621.576	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4297M	2004	NDM	Exploration	1046	2004	516817	1401531.853	2158191.26	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4298M	2004	NDM	Exploration	110	2004	516817	1400988.117	2158039.51	S0035035W21	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
4299M	2004	NDM	Exploration	901	2004	516817	1401400.343	2157338.95	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4300	2004	NDM	Exploration	2362	2005	524712	1407155.116	2156858.36	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4301	2004	NDM	Exploration	1220	2004	524712	1407266.263	2156898.067	S0035035W22	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4302	2004	NDM	Exploration	2118	2005	540424	1406998.945	2157335.432	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4303	2004	NDM	Exploration	2259	2005	524712	1406927.667	2156430.556	S0035035W22	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4304	2004	NDM	Exploration	1000	2005	516870	1397716.307	2155413.045	S0035035W29	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4305	2004	NDM	Exploration	2111	2004	516812	1404268.206	2157104.763	S0035035W22	7/24/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
4306M	2004	NDM	Exploration	1019	2004	516817	1401085.262	2157391.978	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4307M	2004	NDM	Exploration	980	2005	516818	1402833.092	2157478.996	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4308	2004	NDM	Exploration	879	2004	638840	1366784.356	2115741.307	S0045036W33	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
4309	2004	NDM	Exploration	1989	2005	516874	1402402.792	2155827.679	S0035035W28	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5310M	2005	NDM	Exploration	1072	2005	540399	1405418.184	2158021.087	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5311	2005	NDM	Exploration	3493	2005	524713	1407835.946	2156785.517	S0035035W22	8/11/2017	3-E	Wood Post	8-ft Snow Pole			Grouted and Plugged [7]	Stable	
5312M	2005	NDM	Exploration	523	2005	516819	1404493.955	2158160.535	S0035035W22	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
5313M	2005	NDM	Exploration	1092	2005	516819	1404404.725	2158326.915	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5314M	2005	NDM	Exploration	1007	2005	516819	1404657.634	2157444.457	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5315M	2005	NDM	Exploration	912	2005	524828	1404969.223	2157091.994	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5316	2005	NDM	Exploration	1958	2005	524713	1408223.574	2155903.393	S0035035W22	7/20/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5317M	2005	NDM	Exploration	987	2005	540400	1404833.71	2159239.058	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5318	2005	NDM	Exploration	2923	2005	542567	1406060.099	2156864.058	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5319M	2005	NDM	Exploration	982	2005	516811	1402820.797	2156256.123	S0035035W21	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5320M	2005	NDM	Exploration	1359	2005	516811	1403012.837	2156897.733	S0035035W21	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5321	2005	NDM	Exploration	1868	2005	542568	1406094.569	2157640.971	S0035035W22	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel casing/Plug or Cap	12	Grouted and Plugged [7]	Stable	
5322M	2005	NDM	Exploration	1154	2005	516818	1402482.433	2157871.693	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5323M	2005	NDM	Exploration	922	2005	516812	1403666.911	2156280.906	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5324	2005	NDM	Exploration	4077	2005	540425	1407946.332	2157825.337	S0035035W22	9/17/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing	30	Grouted and Plugged [7]	Stable	
5325	2005	NDM	Exploration	2651	2005	542569	1406213.991	2158732.717	S0035035W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
5326	2005	NDM	Exploration	4283	2005	524712	1406397.123	2156162.881	S0035035W22	9/17/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing	48	Grouted and Plugged [7]	Stable	
5327	2005	NDM	Exploration	4338	2005	524713	1408443.913	2156775.034	S0035035W22	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5328	2005	NDM	Exploration	1988	2005	524826	1404442.461	2154653.905	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5329	2005	NDM	Exploration	1828	2005	516808	1398964.885	2157168.704	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5330	2005	NDM	Monitoring/Study	4211	2005	524714	1409168.11	2156910.727	S0035035W23	10/3/2017	1-D	Wood Post	8-ft Snow Pole	Steel casing/Plug or Cap	48	Grouted and Plugged [7]	Stable	
5331	2005	NDM	Exploration	3946	2005	540431	1407777.801	2158819.836	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5332	2005	NDM	Exploration	4206	2005	540426	1408882.802	2157830.969	S0035035W23	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5333	2005	NDM	Exploration	4175	2005	524714	1410058.178	2156848.128	S0035035W23	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5334	2005	NDM	Exploration	3793	2006	524714	1408843.228	2155997.479	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
5335	2005	NDM	Exploration	4358	2006	524715	1410492.65	2156928.973	S0035035W23	9/17/2017	1-E	Wood Post				Grouted and Plugged [7]	Stable	
5336	2005	NDM	Exploration	4228	2006	540426	1410071.524	2158084.822	S0035035W23	9/17/2017	1-E	Wood Post	8-ft Snow Pole	Steel casing/Plug or Cap	24	Grouted and Plugged [7]	Stable	
5337	2005	NDM	Exploration	4198	2006	524714	1409809.419	2156992.819	S0035035W23	10/3/2017	1-E	Casing	8-ft Snow Pole	Steel casing/Plug or Cap	18	Grouted and Plugged [7]	Stable	Reclassified as active site
6338	2006	NDM	Exploration	4082	2006	524713	1408119.584	2156129.491	S0035035W22	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
6339	2006	NDM	Exploration	5085	2006	642364	1408863.844	2155082.952	S0035035W26	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6340	2006	NDM	Exploration	1228	2007	642364	1410570.492	2155405.419	S0035035W26	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
6341	2006	NDM	Exploration	4161	2006	540432	1409468.753	2158949.185	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
6342	2006	NDM	Exploration	3581	2006	524698	1406778.977	2154834.392	S0035035W27	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
6343	2006	NDM	Exploration	5002	2006	524716	1412089.668	2156922.104	S0035035W23	10/3/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing	42	Grouted and Plugged [7]	Stable	
6344	2006	NDM	Monitoring/Study	5700	2006	540427	1411362.081	2157865.426	S0035035W23	9/17/2017	1-E	Casing	8-ft Snow Pole	Steel Casing/Water Valve	12	Grouted and Plugged [7]	Stable	
6345	2006	NDM	Exploration	3227	2006	642364	1410155.566	2155480.34	S0035035W26	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
6346	2006	NDM	Exploration	4723	2006	540433	1410680.14	2158970.642	S0035035W23	8/11/2017	3-E					Grouted and Plugged [7]	Stable	
6347	2006	NDM	Exploration	5395	2007	642364	1410252.412	2154514.318	S0035035W26	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6348	2006	NDM	Exploration	5663	2007	524685	1407680.223	2153536.612	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
6349	2006	NDM	Exploration	4053	2007	524714	1408781.678	2156214.155	S0035035W23	9/17/2017	3-E					Grouted and Plugged [7]	Stable	
6350	2006	NDM	Exploration	4098	2007	540432	1409518.868	2159695.864	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
6351	2006	NDM	Exploration	2781	2007	524668	1406400.451	2152535.264	S0035035W27	7/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6352	2006	NDM	Exploration	1206	2007	524669	1407797.032	2152286.602	S0035035W27	7/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6353	2006	NDM	Exploration	4016	2007	524669	1407799.232	2152286.794	S0035035W27	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6354	2007	NDM	Exploration	5150	2007	540433	1410960.229	2159399.397	S0035035W23	7/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6355	2006	NDM	Exploration	4047	2007	524685	1407644.991	2154169.707	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
6356	2007	NDM	Exploration	6425	2007	642354	1408869.241	2153004.17	S0035035W26	7/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7357	2007	NDM	Exploration	4109	2007	540437	1408597.157	2160601.296	S0035035W22	7/16/2017	3-E					Grouted and Plugged [7]	Stable	
7358	2007	NDM	Exploration	5998	2007	540439	1410828.267	2160983.16	S0035035W23	9/16/2017	3-E					Grouted and Plugged [7]	Stable	
7359	2007	NDM	Exploration	4195	2007	524699	1408077.1	2154525.296	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
7360	2007	NDM	Exploration	4000	2007	524713	1408146.436	2156425.036	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7361	2007	NDM	Exploration	5288	2007	540437	1408365.124	2159860.056	S0035035W22	7/26/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7362	2007	NDM	Exploration	4947	2007	540430	1407525.041	2158793.431	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7363	2007	NDM	Exploration	4028	2007													

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
7380	2007	PLP	Exploration	1323	2008	524684	1407341.972	2153380.193	S0035035W27	9/15/2017	3-E					Grouted and Plugged [7]	Stable	
7381	2007	PLP	Exploration	4589	2008	524714	1409980.081	2156414.62	S0035035W23	10/3/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
7382	2007	PLP	Exploration	3955	2008	540426	1408820.287	2158228.239	S0035035W23	10/3/2017	1-E	Wood Post	8-ft Snow Pole	Steel casing/Plug or Cap	18		Stable	Reclassified as active site
7383	2007	PLP	Exploration	3637	2008	524713	1407609.1	2155797.228	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7384	2007	PLP	Exploration	4042.5	2008	524699	1407811.749	2155186.72	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7385	2007	PLP	Exploration	4206	2008	540426	1409000.026	2157618.629	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
7386	2008	PLP	Exploration	5901	2008	524684	1407342.562	2153380.446	S0035035W27	9/15/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable; additional reclamation in 2018	Grouted and plugged in 2017 (repairs)
7387	2008	PLP	Monitoring/Study	4722	2008	642364	1408961.93	2155207.193	S0035035W26	8/30/2013	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7388	2007	PLP	Exploration	3934	2008	524713	1408254.436	2155901.369	S0035035W22	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7389	2007	PLP	Exploration	3366	2008	540431	1408185.259	2158787.952	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7390M	2007	PLP	Exploration	1199	2008	516810	1400873.078	2157011.756	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7391M	2007	PLP	Exploration	1220	2008	516817	1401090.102	2157593.608	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
7392M	2007	PLP	Exploration	1250	2008	516817	1401092.354	2158144.695	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7393	2007	PLP	Exploration	4446	2008	540426	1409429.891	2158339.087	S0035035W23	7/19/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7394	2008	PLP	Exploration	2940	2008	642364	1408859.644	2153178.275	S0035035W26	7/19/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7395M	2007	PLP	Exploration	1113	2008	516823	1403566.379	2158729.161	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7396M	2007	PLP	Exploration	1050	2008	516818	1402947.37	2157614.002	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
7397M	2007	PLP	Exploration	1080	2008	516811	1402385.844	2156773.073	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7398M	2007	PLP	Exploration	1177	2008	516818	1402392.183	2158386.514	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7399M	2007	PLP	Exploration	1039	2008	516812	1403841.664	2156712.946	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
7400M	2007	PLP	Exploration	1040	2008	540399	1405681.851	2157598.61	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8401	2008	PLP	Exploration	3861	2008	524713	1408442.617	2156993.487	S0035035W22	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8402	2008	PLP	Exploration	5111	2008	540438	1410008.869	2159798.523	S0035035W23	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8403	2008	PLP	Exploration	4278	2008	540431	1408241.368	2159378.354	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8404	2008	PLP	Exploration	3479	2008	542566	1406082.759	2154782.394	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8405	2008	PLP	Exploration	5091	2008	540428	1411801.378	2158189.896	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8406	2008	PLP	Exploration	5148	2008	540438	1410010.139	2159799.171	S0035035W23	7/19/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8407	2008	PLP	Exploration	4362	2008	524669	1407747.534	2152653.394	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8408	2008	PLP	Exploration	1448	2008	540436	1407591.733	2159951.044	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8409	2008	PLP	Exploration	3343	2008	524698	1407186.696	2155197.789	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8410	2008	PLP	Exploration	4437	2008	524716	1411502.999	2156331.41	S0035035W23	10/3/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Water Valve	30		Stable	
8411	2008	PLP	Exploration	4398	2008	540436	1407591.693	2159951.547	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8412	2008	PLP	Exploration	4971	2008	642364	1408854.982	2153947.096	S0035035W26	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8413	2008	PLP	Exploration	4471	2008	540426	1409694.736	2157600.01	S0035035W23	9/17/2017	1-D	Casing	8-ft Snow Pole	Steel casing/Plug or Cap	42		Stable	Reclassified as active site
8414	2008	PLP	Exploration	4488.5	2009	642364	1409703.426	2155202.625	S0035035W26	8/1/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8415	2008	PLP	Exploration	4929	2008	642364	1409617.796	2154768.568	S0035035W26	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8416	2008	PLP	Exploration	5007	2008	540401	1406028.075	2160627.395	S0035035W22	8/11/2017	3-E	Wood Post	8-ft Snow Pole			Grouted and Plugged [7]	Stable	
8417	2008	PLP	Monitoring/Study	4050	2008	524713	1408707.751	2156139.54	S0035035W22	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8418	2008	PLP	Exploration	4546	2009	524684	1407183.728	2154216.538	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8419	2008	PLP	Exploration	4332	2008	540443	1408118.809	2161692.033	S0035035W15	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8420	2008	PLP	Exploration	5038	2009	642364	1409607.375	2155030.673	S0035035W26	8/1/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8421	2008	PLP	Exploration	5078	2008	640428	1412027.822	2158110.988	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8422	2008	PLP	Monitoring/Study	4839	2009	524699	1407856.475	2155145.961	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8423	2008	PLP	Exploration	5636	2009	524716	1412076.977	2156907.988	S0035035W23	9/17/2017	1-D	Wood Post	8-ft Snow Pole	Steel Casing	18		Stable	Reclassified as active site
8424M	2008	PLP	Exploration	687	2008	516821	1401389.43	2158591.217	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8425M	2008	PLP	Exploration	878	2008	516817	1402006.432	2158395.664	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8426M	2008	PLP	Exploration	750	2008	516816	1400828.958	2157931.074	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8427M	2008	PLP	Exploration	920	2008	516817	1401309.47	2157880.997	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8428M	2008	PLP	Exploration	640	2008	516809	1400289.947	2157035.049	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8429M	2008	PLP	Exploration	730	2009	516809	1400805.449	2156731.609	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8430	2008	PLP	Exploration	4376	2009	524823	1405886.843	2152579.605	S0035035W27	7/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8431M	2008	PLP	Exploration	852	2009	516810	1401911.409	2157008.876	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8432M	2008	PLP	Exploration	767	2009	516810	1401643.987	2156060.479	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8433M	2008	PLP	Exploration	660	2009	516874	1402203.615	2155701.446	S0035035W28	9/15/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable	
8434M	2008	PLP	Exploration	1150	2009	524828	1405379.601	2156448.411	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8435M	2008	PLP	Exploration	1097	2009	540430	1406442.748	2159045.725	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8436	2008	PLP	Exploration	3591	2009	524698	1406783.962	2154840.642	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8437M	2008	PLP	Exploration	1060	2009	540400	1405296.794	2158819.276	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8438	2008	PLP	Monitoring/Study	3184	2009	524714	1409109.084	2156249.709	S0035035W23	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8439M	2008	PLP	Exploration	931	2009	516812	1404647.502	2157026.982	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8440M	2008	PLP	Exploration	1667	2009	540424	1406461.199	2157297.718	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8441M	2008	PLP	Exploration	1721	2009	524712	1406680.121	2156592.96	S0035035W22	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
8442	2008	PLP	Exploration	3118	2009	524827	1405282.276	2155460.279	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8443	2008	PLP	Monitoring/Study	2911	2009	540424	1407276.206	2158139.47	S0035035W22	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
8444	2008	PLP	Monitoring/Study	2935	2009	524826	1403936	2154804.569	S0035035W27	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9445	2009	PLP	Exploration	1004	2009	524820	1404513.48	2151284.33	S0035035W27	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
9446	2009	PLP	Exploration	1002	2009	516856	1403335.4	2151673.99	S0035035W28	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
9447	2009	PLP	Exploration	1203	2009	516856	1402316.44	2150868.43	S0035035W28	9/17/2017	1-E	Wood Post	8-ft Snow Pole	Steel casing/Plug or Cap	18		Stable	Reclassified as active site
9448	2009	PLP	Exploration	1002	2009	524818</												

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
9465	2009	PLP	Exploration	1429	2010	644243	1410352.78	2173024.65	S0035035W02	8/1/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9466	2009	PLP	Exploration	1205	2010	524816	1397381.34	2150162.6	S0035035W32	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9467	2009	PLP	Exploration	1200	2009	524860	1399407.13	2168239.56	S0035035W09	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9468	2009	PLP	Exploration	1208	2009	516846	14003763.13	2149067.47	S0035035W33	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
9469	2009	PLP	Exploration	1188	2010	567049	1399417.95	2172471.02	S0035035W04	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9470	2009	PLP	Exploration	120	2010	540407	1405086.67	2168937.15	S0035035W10	7/14/2017	3-E	Wood Post				Backfilled [5]	Stable	
9471	2009	PLP	Exploration	1005	2010	540407	1405087.51	2168936.21	S0035035W10	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9472	2009	PLP	Exploration	1161	2010	524846	1400354.91	2164718.01	S0035035W16	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9473	2009	PLP	Exploration	711.5	2010	531448	1394898.15	2161017.13	S0035035W20	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9474	2009	PLP	Exploration	40	2010	540455	1407879.55	2163863.62	S0035035W15	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9475	2009	PLP	Monitoring/Study	1198	2010	540442	1406679.89	2161885.08	S0035035W15	9/15/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable; additional reclamation in 2018	Grouted and plugged in 2017 (repairs)
9476	2009	PLP	Exploration	1200	2010	540467	1408377.01	2166734.65	S0035035W10	7/14/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
9477	2009	PLP	Exploration	1200	2010	540455	1407879.55	2163863.62	S0035035W15	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
10478	2010	PLP	Exploration	759.8	2010	643915	1399387.036	2121641.003	S0045035W28	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10479	2010	PLP	Exploration	1158	2010	566855	1398038.431	2134301.157	S0045035W16	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10480	2010	PLP	Exploration	1028	2010	531366	1391495.613	2135072.51	S0045035W07	8/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10481	2010	PLP	Exploration	1098	2010	643915	1397914.294	2122132.582	S0045035W28	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10482	2010	PLP	Exploration	1197	2010	638840	1366021.452	2114950.188	S0045036W33	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10483	2010	PLP	Exploration	1200	2010	566834	1394477.513	2132895.442	S0045035W17	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10484	2010	PLP	Exploration	972	2010	638853	1364972.798	2113932.052	S0055037W01	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10485	2010	PLP	Exploration	1197	2010	638840	1368031.189	2116660.454	S0045036W33	9/15/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable	
10486	2010	PLP	Exploration	1200	2010	643922	1402449.944	2124336.477	S0045035W21	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10487	2010	PLP	Exploration	1207	2010	638853	1364304.225	2112118.749	S0055037W01	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10488	2010	PLP	Exploration	1080	2010	531355	1387711.539	2132842.944	S0045035W18	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10489	2010	PLP	Exploration	1077	2010	638854	1367393.292	2112914.649	S0055036W06	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10490	2010	PLP	Exploration	1101	2010	524765	1397708.842	2135957.892	S0045035W08	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10491	2010	PLP	Exploration	1197	2010	638838	1360631.004	2115697.273	S0045036W32	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10492	2010	PLP	Exploration	1200	2010	644255	1413075.883	2168267.817	S0035035W11	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10493	2010	PLP	Exploration	1207	2010	566697	1382362.751	2128038.557	S0045036W24	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10494	2010	PLP	Exploration	1147	2010	567048	1397993.598	2172242.798	S0035035W05	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10495	2010	PLP	Exploration	1147	2010	638815	1374427.685	2119626.41	S0045036W27	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10496	2010	PLP	Exploration	1102	2010	638838	1362688.117	2115701.309	S0045036W32	8/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10497	2010	PLP	Exploration	1386	2010	642444	1380441.342	2163454.215	S0035036W14	8/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10498	2010	PLP	Exploration	1465	2010	638809	1359674.473	2121037.893	S0045036W30	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
10499	2010	PLP	Exploration	929	2010	566993	1386171.126	2165682.304	S0035036W13	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10500	2010	PLP	Exploration	1275	2010	638851	1360312.318	2114329.004	S0055037W02	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10501	2010	PLP	Exploration	1067	2010	531464	1394891.516	2165053.274	S0035035W17	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10502	2010	PLP	Exploration	1458	2010	643909	1398744.421	2120636.727	S0045035W28	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10503	2010	PLP	Exploration	845	2010	524844	1397952.308	2164309.513	S0035035W17	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10504	2010	PLP	Exploration	1198	2011	643915	1399393.238	2124229.222	S0045035W28	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10505	2010	PLP	Exploration	586	2010	531447	1393963.999	2160920.922	S0035035W20	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10506	2010	PLP	Exploration	882	2011	566738	1384209.241	2125332.501	S0045036W24	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10507	2010	PLP	Exploration	1524	2011	638823	1358843.062	2119803.561	S0045036W31	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10508	2010	PLP	Exploration	935	2010	566971	1385523.476	2159445.729	S0035036W24	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10509	2010	PLP	Exploration	968	2010	642444	1381539.478	2161965.362	S0035036W14	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10510	2010	PLP	Exploration	1084	2010	638823	1358899.126	2118616.426	S0045036W31	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10511	2010	PLP	Exploration	1286	2011	638809	1360480.337	2120107.251	S0045036W30	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10512	2010	PLP	Exploration	1022	2011	642442	1376133.055	2163921.894	S0035036W15	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10513	2010	PLP	Exploration	1257	2011	638811	1364311.592	2121422.385	S0045036W29	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10514	2010	PLP	Exploration	1028	2010	525849	1401132.125	2166091.212	S0035035W16	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10515	2010	PLP	Exploration	1157	2011	638827	1369089.969	2118660.797	S0045036W33	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10516	2010	PLP	Exploration	1107	2010	567021	1388832.177	2170193.511	S0035035W07	7/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10517	2010	PLP	Exploration	1377	2011	638810	1363147.046	2121207.311	S0045036W29	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10518	2010	PLP	Exploration	443	2011	516961	1400519.794	2141330.814	S0045035W04	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
10519	2010	PLP	Exploration	1127	2010	638815	1374232.137	2121902.821	S0045036W27	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10520	2010	PLP	Exploration	1278	2011	516961	1400519.069	2141330.727	S0045035W04	9/17/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10521	2010	PLP	Exploration	1127	2010	644220	1361735.984	2108896.835	S0055037W12	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10522	2010	PLP	Exploration	1207	2010	566332	1386448.987	2113710.677	S0055036W03	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10523	2010	PLP	Exploration	1500	2010	524752	1400438.619	2132136.618	S0045035W16	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10524	2010	PLP	Exploration	1207	2010	643910	1400414.978	2119205.472	S0045035W28	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
10525	2010	PLP	Exploration	1208	2011	644206	1408482.936	2120137.807	S0045035W26	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
11526	2010	PLP	Exploration	227	2011	516810	1401883.7	2157109.86	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
11527	2011	PLP	Exploration	2700	2011	516810	1401883.7	2157109.86	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
11528	2011	PLP	Exploration	1530	2011	642435	1378433.16	2156986.91	S0035036W23	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
11529	2011	PLP	Exploration	3482	2011	516873	1401822.86	2154772.07	S0035035W28	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
11530	2011	PLP	Exploration	1000	2011	642429	1375408.98	2154767.56	S0035036W27	9/15/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
11531	2011	PLP	Monitoring/Study	2458	2011	516811	1403222.88	2156346.41	S0035035W21	9/16/2017	1-E	Wood Post	Steel casing/Plug or Cap	18		Grouted and Plugged [7]	Stable	Reclassified as active site
11532	2011	PLP	Exploration	637	2011	642437	1373357.8	2159450.16	S0035036W22	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
11533	2011	PLP	Exploration	4812	2011	524699	1407981.61	2155476.73	S0035035W27	9/17/2017	3							

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
12548	2012	PLP	Monitoring/Study	1106	2013	524826	1404247.845	2155482.208	S0035035W27	8/11/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing	15		Stable	
12549	2012	PLP	Exploration	1299	2012	516815	1399366.636	2157664.953	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12550	2012	PLP	Exploration	1546	2013	552914	2096412.511	1395370.238	S0055036W24	9/15/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable	
12551	2012	PLP	Monitoring/Study	3006	2013	524827	1404755.454	2155200.87	S0035035W27	9/16/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing	12		Stable	
12552 [8]										#N/A	#N/A							
12553	2012	PLP	Exploration	1753.5	2012	516809	1400059.314	2156583.823	S0035035W21	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12554	2012	PLP	Exploration	1030	2013	644414	1359194.599	2178913.294	S0025036W31	7/13/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12555	2012	PLP	Exploration	1646	2013	516810	1401046.81	2156175.467	S0035035W21	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	Casing removed
12556	2012	PLP	Exploration	1278	2013	644414	1361348.919	2179198.639	S0025036W31	7/13/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12557	2012	PLP	Exploration	1188	2013	516873	1401030.273	2154754.254	S0035035W28	9/16/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12558	2012	PLP	Exploration	753.5	2013	649733	1332769.33	2172818.968	S0035037W08	8/30/2013	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12559	2012	PLP	Exploration	682	2013	516807	1397972.683	2156123.782	S0035035W20	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12560	2012	PLP	Exploration	1479	2013	524787	1396504.185	2141929.252	S0045035W05	8/16/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
12561	2012	PLP	Exploration	1117	2013	516807	1397967.403	2156618.83	S0035035W20	7/30/2017	3-D	Wood Post				Grouted and Plugged [7]	Stable	
12562	2012	PLP	Exploration	418	2013	516807	1398001.148	2157011.095	S0035035W20	8/11/2017	3-E	Wood Post				Grouted and Plugged [7]	Stable	
GH04-001	2004	NDM	Monitoring/Study	197	2004	643933	1386179.412	2171584.481	S0035036W12	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	11.64		Stable	
GH04-002	2004	NDM	Monitoring/Study	125	2004	540423	1405880.703	2170919.112	S0035035W10	7/13/2017	1-E	Monument		Steel Casing/Monument	7.32		Stable	
GH04-003	2004	NDM	Monitoring/Study	405	2004	643922	1400582.038	2125932.278	S0045035W21	7/13/2017	1-E	Monument		Steel Casing/Monument	7.44		Stable	
GH04-004	2004	NDM	Monitoring/Study	304	2004	566638	1383248.191	2123685.942	S0045036W25	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	6.48		Stable	
GH04-005	2004	NDM	Monitoring/Study	210	2004	638811	1365294.721	2121512.331	S0045036W29	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	12.24		Stable	
GH04-006	2004	NDM	Monitoring/Study	213	2004	516844	1402985.621	2146959.178	S0035035W33	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	17.4		Stable	
GH04-007	2004	NDM	Monitoring/Study	110	2004	642446	1382512.408	2164276.637	S0035036W14	8/15/2016	3-E					Grouted and Plugged [7]	Stable	
GH04-008	2004	NDM	Monitoring/Study	135	2004	642418	1373554.055	2149963.472	S0035036W34	9/15/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap	4.08		Stable	
GH04-009	2004	NDM	Monitoring/Study	115	2004	640095	1377954.165	2135077.341	S0045036W14	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
GH04-010	2004	NDM	Monitoring/Study	340	2004	643914	1395410.091	2123101.283	S0045035W29	7/13/2017	1-E	Monument		Steel Casing/Monument	3.96		Stable	
GH04-011	2004	NDM	Monitoring/Study	170	2004	567855	1406016.435	2128320.842	S0045035W22	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	7.44		Stable	
GH04-012	2004	NDM	Monitoring/Study	36	2004	643913	1392743.753	2123132.831	S0045035W29	7/25/2016	3-E					Backfilled [5]	Stable	
GH04-012A	2004	NDM	Monitoring/Study	130	2004	643913	1393588.742	2122286.271	S0045035W29	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	3		Stable	
GH04-013	2004	NDM	Monitoring/Study	210	2004	643902	1392019.847	2117580.751	S0045035W31	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	12		Stable	
GH04-014	2004	NDM	Monitoring/Study	185	2004	566569	1382416.844	2121519.946	S0045036W25	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	2.52		Stable	
GH04-015	2004	NDM	Monitoring/Study	125	2004	566655	1380423.956	2123254.783	S0045036W26	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
GH04-016	2004	NDM	Monitoring/Study	110	2004	566737	1381837.721	2125117.155	S0045036W24	6/29/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Monument	10.92		Stable	
GH04-017	2004	NDM	Monitoring/Study	195	2004	538786	1381593.211	2126016.392	S0045036W23	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	5.4		Stable	
GH04-018	2004	NDM	Monitoring/Study	177	2004	566607	1382119.535	2126851.246	S0045036W24	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	2.64		Stable	
GH04-019	2004	NDM	Monitoring/Study	120	2004	640095	1377771.816	2133668.227	S0045036W14	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	20.28		Stable	
GH04-020	2004	NDM	Monitoring/Study	105	2004	644279	1380419.612	2135284.213	S0045036W11	8/9/2013	1-E	Monument		Steel Casing/Monument	17.88		Stable	
GH04-021	2004	NDM	Monitoring/Study	105	2004	644277	1376083.698	2135310.286	S0045036W10	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
GH04-022	2004	NDM	Monitoring/Study	150	2004	566865	1382097.885	2136338.091	S0045036W12	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	0		Stable	
GH04-023	2004	NDM	Monitoring/Study	119.5	2004	642446	1381014.64	2164416.894	S0035036W14	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	17.04		Stable	
GH04-024	2004	NDM	Monitoring/Study	120	2004	566985	1383094.122	2165121.486	S0035036W13	8/15/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
GH04-025	2004	NDM	Monitoring/Study	185	2004	566981	1383711.501	2163357.987	S0035036W13	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	7.2		Stable	
GH04-026	2004	NDM	Monitoring/Study	135	2005	524829	1396244.746	2158942.161	S0035035W20	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	1.92		Stable	
GH04-027	2004	NDM	Monitoring/Study	125	2004	516813	1395817.398	2157550.194	S0035035W20	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	26.04		Stable	
GH04-028	2004	NDM	Monitoring/Study	145	2005	516951	1398090.824	2137380.19	S0045035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	1.92		Stable	
GH04-029	2004	NDM	Monitoring/Study	45	2005	516948	1399084.609	2135591.037	S0045035W09	7/13/2017	3-E					Backfilled [5]	Stable	
GH04-029A	2004	NDM	Monitoring/Study	159	2005	516948	1399082.372	2135596.273	S0045035W09	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	1.08		Stable	
GH04-030	2004	NDM	Monitoring/Study	175	2005	566834	1394721.54	2132942.944	S0045035W17	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	7.68		Stable	
GH04-031	2004	NDM	Monitoring/Study	195	2004	524760	1400679.877	2133912.445	S0045035W16	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	2.28		Stable	
GH04-032	2004	NDM	Monitoring/Study	135	2004	524756	1401400.011	2132210.489	S0045035W16	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	2.04		Stable	
GH04-033	2004	NDM	Monitoring/Study	335	2005	643926	1399306.726	2129091.446	S0045035W21	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	3.6		Stable	
GH04-034	2004	NDM	Monitoring/Study	295	2004	643919	1394853.66	2125647.611	S0045035W20	7/25/2016	3-E	Wood Post				Grouted and Plugged [7]	Stable	
GH04-035	2004	NDM	Monitoring/Study	190	2005	643921	1397713.311	2126745.952	S0045035W21	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	6.72		Stable	
GH04-036	2004	NDM	Monitoring/Study	155	2005	643907	1392907.738	2119651.062	S0045035W29	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
GH04-037	2004	NDM	Monitoring/Study	295	2005	643905	1389713.099	2119794.874	S0045035W30	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	6.6		Stable	
GH04-038	2004	NDM	Monitoring/Study	190	2004	566532	1386306.241	2120506.915	S0045036W25	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	1.2		Stable	
GH04-039	2004	NDM	Monitoring/Study	120	2005	643911	1389231.256	2122704.719	S0045035W30	7/13/2017	1-E	Monument		Steel Casing/Monument	0		Stable	
GH04-040	2004	NDM	Monitoring/Study	95	2004	566640	1386099.664	2123815.026	S0045036W25	7/25/2016	3-E					Backfilled [5]	Stable	
GH04-040A	2004	NDM	Monitoring/Study	255	2004	566640	1386139.394	2123860.218	S0045036W25	7/25/2016	3-E					Grouted and Plugged [7]	Stable	
GH04-041	2004	NDM	Monitoring/Study	125	2004	524763	1405003.465	2133603.733	S0045035W15	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	4.68		Stable	
GH04-042	2004	NDM	Monitoring/Study	150	2004	524768	1404565.985	2135122.128	S0045035W10	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	4.8		Stable	
GH04-043																		

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes	
GH06-072	2006	NDM	Monitoring/Study	215	2006	524808	1403789.743	2147128.202	S0035035W34	9/17/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap	22.68		Stable		
GH06-073	2006	NDM	Monitoring/Study	158.5	2006	524595	1406063.079	2146875.399	S0035035W34	9/17/2017	3-E					Grouted and Plugged [7]	Stable	Casing removed	
GH06-074	2006	NDM	Monitoring/Study	140	2006	524596	1407904.629	2147513.692	S0035035W34	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			25.08	Stable	
GH06-075	2006	NDM	Monitoring/Study	414.5	2007	516953	1400526.816	2136597.363	S0045035W09	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			33.36	Stable	
GH06-076	2006	NDM	Monitoring/Study	274.5	2006	516950	1401320.265	2135577.865	S0045035W09	8/11/2013	1-E	Monument		Steel Casing/Monument			30.96	Stable	
GH06-077	2006	NDM	Monitoring/Study	482	2006	516949	1400131.093	2135458.028	S0045035W09	8/11/2013	1-E	Monument		Steel Casing/Monument			31.2	Stable	
GH06-078	2006	NDM	Monitoring/Study	149	2007	524714	1409794.115	2155946.301	S0035035W23	9/17/2017	3-E					Grouted and Plugged [7]	Stable		
GH06-079	2006	NDM	Monitoring/Study	120	2006	642364	1410562.221	2155392.95	S0035035W26	8/3/2017	1-E	Casing	8-ft Snow Pole	Steel casing/Plug or Cap			36	Stable	Reclassified as active site
GH06-080	2006	NDM	Monitoring/Study	188.5	2007	524698	1406799.942	2154863.876	S0035035W27	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			31	Stable	
GH07-081	2007	PLP	Monitoring/Study	164.5	2007	642440	1382565.817	2161332.286	S0035036W23	9/15/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap			36.6	Stable	
GH07-082	2007	PLP	Monitoring/Study	215	2007	642443	1379583.623	2162942.037	S0035036W14	8/10/2013	1-E	Monument		Steel Casing/Monument			35.76	Stable	
GH07-083	2007	PLP	Monitoring/Study	164.5	2007	642442	1374824.858	2163509.385	S0035036W15	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			28.08	Stable	
GH07-084	2007	PLP	Monitoring/Study	165	2007	553542	1375762.391	2164988.469	S0035036W15	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			36.36	Stable	
GH07-085	2007	PLP	Monitoring/Study	154.5	2007	642443	1377732.729	2163903.879	S0035036W14	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			36.6	Stable	
GH07-086	2007	PLP	Monitoring/Study	165	2007	642437	1372867.754	2161120.808	S0035036W22	8/10/2013	1-E	Monument		Steel Casing/Monument			26.64	Stable	
GH07-087	2007	PLP	Monitoring/Study	260	2007	642437	1372353.55	2159295.68	S0035036W22	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			29.88	Stable	
GH07-088	2007	PLP	Monitoring/Study	155	2007	642441	1372730.124	2162437.235	S0035036W15	8/10/2013	1-E	Monument		Steel Casing/Monument			32.52	Stable	
GH07-089	2007	PLP	Monitoring/Study	154.1	2007	642420	1367910.547	2153619.02	S0035036W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			51.6	Stable	
GH07-090	2007	PLP	Monitoring/Study	170	2007	642416	1367772.548	2151061.026	S0035036W33	8/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			24	Stable	
GH07-091	2007	PLP	Monitoring/Study	155	2007	642416	1368765.366	2149767.098	S0035036W33	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			39	Stable	
GH07-092	2007	PLP	Monitoring/Study	160	2007	642417	1370764.808	2149447.327	S0035036W33	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			43.8	Stable	
GH07-093	2007	PLP	Monitoring/Study	205	2007	642418	1373639.993	2149128.762	S0035036W34	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			42.72	Stable	
GH07-094	2007	PLP	Monitoring/Study	139	2007	642419	1374743.145	2148733.327	S0035036W34	8/9/2013	1-E	Monument		Steel Casing/Monument			44.76	Stable	
GH07-095	2007	PLP	Monitoring/Study	129.8	2007	642430	1379810.507	2155439.693	S0035036W26	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			35.4	Stable	
GH07-096	2007	PLP	Monitoring/Study	195	2008	642431	1381752.557	2156210.551	S0035036W26	8/10/2013	1-E	Monument		Steel Casing/Monument			46.2	Stable	
GH07-097	2007	PLP	Monitoring/Study	185	2007	566953	1382608.647	2154726.287	S0035036W25	8/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			24	Stable	
GH07-098	2007	PLP	Monitoring/Study	229.5	2008	566950	1384912.694	2152902.133	S0035036W25	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			34.56	Stable	
GH07-099	2007	PLP	Monitoring/Study	160	2008	566955	1385450.921	2154210.09	S0035036W25	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			38.4	Stable	
GH07-100	2007	PLP	Monitoring/Study	179.5	2008	566946	1384518.431	2151718.465	S0035036W25	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			38.4	Stable	
GH07-101	2007	PLP	Monitoring/Study	119.5	2008	566994	1387533.358	2166748.817	S0035036W13	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			38.88	Stable	
GH07-102	2007	PLP	Monitoring/Study	133	2008	567007	1383762.883	2168707.375	S0035036W12	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			30.6	Stable	
GH07-103	2007	PLP	Monitoring/Study	130	2008	566987	1386316.031	2165174.042	S0035036W13	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			36.48	Stable	
GH07-104	2007	PLP	Monitoring/Study	195	2008	524685	1408702.633	2153136.385	S0035035W27	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			39	Stable	
GH07-105	2007	PLP	Monitoring/Study	170	2008	524668	1406897.562	2152552.068	S0035035W27	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			33.48	Stable	
GH07-106	2007	PLP	Monitoring/Study	115	2008	524649	1406499.985	2150670.451	S0035035W27	9/17/2017	1-D	Casing	8-ft Snow Pole	Steel Casing/Monument			26.04	Stable	
GH08-107	2008	PLP	Monitoring/Study	355	2008	524699	1407556.95	2154629.547	S0035035W27	9/17/2017	1-D	Casing	8-ft Snow Pole	Steel Casing			30	Stable	
GH08-108	2008	PLP	Monitoring/Study	75	2008	540427	1410500.71	2157069.087	S0035035W23	6/29/2017	1-E	Casing	8-ft Snow Pole	Steel Casing/Water Valve			18	Stable	
GH08-109	2008	PLP	Monitoring/Study	139.5	2008	524685	1408606.954	2154403.861	S0035035W27	8/9/2013	1-E	Monument		Steel Casing/Monument			42.72	Stable	
GH08-110	2008	PLP	Monitoring/Study	75	2008	540426	1409305.416	2157259.197	S0035035W23	9/17/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap			25.32	Stable	
GH08-111	2008	PLP	Monitoring/Study	119.5	2008	524685	1407626.615	2153774.22	S0035035W27	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			48	Stable	
GH08-112	2008	PLP	Monitoring/Study	380	2008	524713	1408340.802	2155882.418	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			32.64	Stable	
GH08-113	2008	PLP	Monitoring/Study	105	2008	524650	1408278.082	2151708.235	S0035035W27	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			17.76	Stable	
GH08-114	2008	PLP	Monitoring/Study	34.7	2008	540431	1408781.049	2159451.935	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			43.08	Stable	
GH08-115	2008	PLP	Monitoring/Study	200	2008	642364	1409718.586	2154431.312	S0035035W26	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			26.28	Stable	
GH08-116	2008	PLP	Monitoring/Study	30	2008	540432	1409245.013	2158612.768	S0035035W23	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			45	Stable	
GH08-117	2008	PLP	Monitoring/Study	75	2008	642374	1415033.754	2157484.803	S0035035W24	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			36.12	Stable	
GH08-118	2008	PLP	Monitoring/Study	85	2008	642374	1415045.382	2156297.745	S0035035W24	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			32.88	Stable	
GH08-119	2008	PLP	Monitoring/Study	105	2008	540428	1411549.419	2157798.482	S0035035W23	9/17/2017	1-E	Monument		Steel Casing/Monument			36.24	Stable	
GH08-120	2008	PLP	Monitoring/Study	50	2008	540433	1410536.224	2158438.651	S0035035W23	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			30.36	Stable	
GH08-121	2008	PLP	Monitoring/Study	135	2008	642364	1411364.434	2154708.698	S0035035W26	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			28.68	Stable	
GH08-122	2008	PLP	Monitoring/Study	115	2008	524716	1411477.406	2156616.94	S0035035W23	10/3/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument			35.28	Stable	
GH08-123	2008	PLP	Monitoring/Study	42.6	2008	524821	1404831.653	2151512.066	S0035035W27	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			38.64	Stable	
GH08-124	2008	PLP	Monitoring/Study	155	2008	540452	1412342.426	2163597.153	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			34.32	Stable	
GH08-125	2008	PLP	Monitoring/Study	150	2008	524827	1405927.423	2154974.703	S0035035W27	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			36	Stable	
GH08-126	2008	PLP	Monitoring/Study	65	2008	540451	1411129.408	2163433.789	S0035035W15	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			51.96	Stable	
GH08-127	2008	PLP	Monitoring/Study	155	2008	540460	1407492.961	2165461.798	S0035035W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			28.68	Stable	
GH08-128	2008	PLP	Monitoring/Study	285	2008	531432	1395164.96	2154862.132	S0035035W29	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument			36.6	Stable	
GH																			

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
GH08-169	2008	PLP	Monitoring/Study	499.5	2008	642421	1369359.54	2153063.486	S0035036W28	8/10/2013	1-E	Monument		Steel Casing/Monument	38.16			Stable
GH08-170	2008	PLP	Monitoring/Study	500	2008	642412	1367111.992	2147895.441	S0035036W33	7/26/2016	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	49			Stable
GH08-171	2008	PLP	Monitoring/Study	150	2008	642413	1370411.364	2147240.695	S0035036W33	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	28.56			Stable
GH08-172	2008	PLP	Monitoring/Study	235	2008	642413	1371504.59	2147900.733	S0035036W33	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.04			Stable
GH08-173	2008	PLP	Monitoring/Study	220	2009	642414	1372111.637	2146474.632	S0035036W34	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	27.24			Stable
GH08-174	2008	PLP	Monitoring/Study	170	2009	644258	1373009.881	2145190.781	S0045036W03	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	33			Stable
GH08-175	2008	PLP	Monitoring/Study	145	2009	642414	1373749.319	2147146.486	S0035036W34	8/9/2013	1-E	Monument		Steel Casing/Monument	43.32			Stable
GH08-176	2008	PLP	Monitoring/Study	145	2009	644270	1371615.638	2140250.184	S0045036W10	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.12			Stable
GH08-177	2008	PLP	Monitoring/Study	300	2008	531454	1392383.136	2162765.473	S0035035W18	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.28			Stable
GH08-178	2008	PLP	Monitoring/Study	260	2008	531450	1392234.125	2161568.847	S0035035W18	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.8			Stable
GH08-179	2008	PLP	Monitoring/Study	215	2009	531449	1391461.618	2162014.819	S0035035W18	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.28			Stable
GH08-180	2008	PLP	Monitoring/Study	240	2009	531453	1391006.828	2162954.652	S0035035W18	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.04			Stable
GH08-181	2008	PLP	Monitoring/Study	120	2008	566990	1390020.037	2165357.406	S0035035W18	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42.84			Stable
GH08-182	2008	PLP	Monitoring/Study	165	2008	542601	1388906.635	2160151.941	S0035035W19	8/7/2013	1-E	Monument		Steel Casing/Monument	42.48			Stable
GH08-183	2008	PLP	Monitoring/Study	270	2008	531441	1391073.986	2159866.113	S0035035W19	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.2			Stable
GH08-184	2008	PLP	Monitoring/Study	50	2008	642435	1377776.35	2158752.417	S0035036W23	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.28			Stable
GH08-185	2008	PLP	Monitoring/Study	60	2008	642435	1379059.084	2158948.92	S0035036W23	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	46.32			Stable
GH08-186	2008	PLP	Monitoring/Study	24.5	2008	642439	1379386.572	2160727.311	S0035036W23	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.08			Stable
GH08-187	2008	PLP	Monitoring/Study	145	2008	566969	1383083.145	2159910.246	S0035036W24	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.28			Stable
GH08-188	2008	PLP	Monitoring/Study	90	2009	566970	1384805.081	2159682.359	S0035036W24	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42			Stable
GH08-189	2008	PLP	Monitoring/Study	350	2009	531446	1392769.528	2160624.14	S0035035W19	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.24			Stable
GH08-190	2008	PLP	Monitoring/Study	160	2009	566850	1386093.781	2134335.627	S0045036W13	8/9/2013	1-E	Monument		Steel Casing/Monument	31.8			Stable
GH08-191	2008	PLP	Monitoring/Study	180	2008	531371	1390876.479	2137550.92	S0045035W07	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.28			Stable
GH08-192	2008	PLP	Monitoring/Study	255	2009	531434	1392336.928	2156357.508	S0035035W19	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.36			Stable
GH08-193	2008	PLP	Monitoring/Study	150	2009	566865	1383319.96	2136060.458	S0045036W12	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	33.6			Stable
GH08-194	2008	PLP	Monitoring/Study	225	2009	531423	1392891.843	2153257.61	S0035035W29	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.2			Stable
GH08-195	2008	PLP	Monitoring/Study	165.5	2009	640095	1377408.171	2132718.627	S0045036W14	8/9/2013	1-E	Monument		Steel Casing/Monument	36			Stable
GH08-196	2008	PLP	Monitoring/Study	105	2009	531424	1394473.194	2152343.792	S0035035W29	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	47.88			Stable
GH08-197A	2008	PLP	Monitoring/Study	45	2009	644272	1376956.645	2138198.227	S0045036W11	8/11/2013	1-E	Monument		Steel Casing/Monument	19.56			Stable
GH08-197B	2008	PLP	Monitoring/Study	400	2009	644272	1376948.078	2138184.175	S0045036W11	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	0			Stable
GH08-198	2008	PLP	Monitoring/Study	200	2009	524835	1395936.149	2162342.141	S0035035W17	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.68			Stable
GH08-199	2008	PLP	Monitoring/Study	245	2009	644273	1380180.008	2139427.097	S0045036W11	8/11/2013	1-E	Monument		Steel Casing/Monument	56.64			Stable
GH08-200	2008	PLP	Monitoring/Study	150	2009	524846	1399869.46	2164707.681	S0035035W16	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.4			Stable
GH08-201	2008	PLP	Monitoring/Study	238	2009	516834	1401338.067	2164346.093	S0035035W16	8/7/2013	3-E	Wood Post				Grouted and Plugged [7]		Stable
GH08-202	2008	PLP	Monitoring/Study	125	2009	516836	1404030.996	2163893.166	S0035035W15	8/7/2013	3-E	Wood Post				Grouted and Plugged [7]		Stable
GH08-203	2008	PLP	Monitoring/Study	230	2009	644270	1373795.095	2140308.643	S0045036W10	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	0			Stable
GH08-204	2008	PLP	Monitoring/Study	239.8	2009	642338	1408822.867	2146401.722	S0035035W35	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43.2			Stable
GH08-205	2008	PLP	Monitoring/Study	155	2009	531649	1393051.22	2145204.437	S0045035W05	8/11/2013	1-E	Monument		Steel Casing/Monument	36.36			Stable
GH08-206	2008	PLP	Monitoring/Study	270	2009	531410	1392479.493	2149488.013	S0035035W31	10/3/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	29.88			Stable
GH08-207	2008	PLP	Monitoring/Study	115	2009	642338	1410638.545	2147465.691	S0035035W35	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	47.28			Stable
GH08-208	2008	PLP	Monitoring/Study	200	2009	531414	1392562.991	2150662.234	S0035035W31	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.16			Stable
GH08-209	2008	PLP	Monitoring/Study	165	2009	642334	1409363.915	2144556.732	S0045035W02	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.08			Stable
GH08-210	2008	PLP	Monitoring/Study	145	2009	524595	1407171.193	2146874.867	S0035035W34	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.96			Stable
GH10-211	2010	PLP	Monitoring/Study	50	2010	524836	1397211.021	2161757.529	S0035035W17	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	29.88			Stable
GH10-212	2010	PLP	Monitoring/Study	115	2010	524833	1397588.223	2160441.979	S0035035W20	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.08			Stable
GH10-213	2010	PLP	Monitoring/Study	165	2010	524837	1399036.198	2161546.316	S0035035W16	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.96			Stable
GH10-214	2010	PLP	Monitoring/Study	135	2010	524831	1398287.063	2159461.282	S0035035W21	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	0			Stable
GH10-215	2010	PLP	Monitoring/Study	75	2010	642446	1382647.121	2165467.456	S0035036W14	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	38.28			Stable
GH10-216	2010	PLP	Monitoring/Study	130	2010	642418	1373405.38	2150792.739	S0035036W34	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.2			Stable
GH10-217	2010	PLP	Monitoring/Study	144	2010	516817	1400917.57	2158418.966	S0035035W21	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42			Stable
GH10-218	2010	PLP	Monitoring/Study	143.2	2010	516809	1400730.791	2156963.756	S0035035W21	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34			Stable
GH10-219	2010	PLP	Monitoring/Study	158	2010	540401	1405152.658	2160637.495	S0035035W22	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42			Stable
GH10-220	2010	PLP	Monitoring/Study	600	2010	642412	1366690.022	2148401.018	S0035036W33	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	17			Stable
GH10-221	2010	PLP	Monitoring/Study	139	2010	540400	1405546.613	2159170.91	S0035035W22	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48			Stable
GH10-222	2010	PLP	Monitoring/Study	130	2010	524712	1406600.282	2156961.038	S0035035W22	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32			Stable
GH10-223	2010	PLP	Monitoring/Study	110	2010	516812	1404712.799	2156283.788	S0035035W22	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40			Stable
GH10-224	2010	PLP	Monitoring/Study	80	2010	524824	1403805.843	2154519.304	S0035035W27	8/11/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45			Stable
GH10-225	2010	PLP	Monitoring/Study	600	2011	642412	1367812.412	2147631.743	S0035036W33	8/9/2013	1-E	Casing	8-ft Snow Pole	Steel Casing	50.28			Stable
GH10-226	2010	PLP	Monitoring/Study	160	2011	516969	1403371.721	2142009.434	S0045035W03	9/17/2017	3-E					Grouted and Plugged [7]		Casing removed
GH10-227	2010	PLP	Monitoring/Study	200	2011	642376	1421653.327	2155963.788	S0035034W19	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.48			Stable
GH10-228	2010	PLP	Monitoring/Study	240	2011	642385	1421905.008	2158170.346	S0035034W19	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	29.88			Stable
GH11-229	2011	PLP	Monitoring/Study	174	2011	540447	1413848.71	2161612.06	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.04			Stable
GH11-230	2011	PLP	Monitoring/Study	173	2011	642400	1420459.9	2164329.67	S0035034W18	8/8/2013	3-E					Grouted and Plugged [7]		Stable
GH11-231	2011	PLP	Monitoring/Study	114	2011	540441	1413027.18	2160039.78	S0035035W23	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.76			Stable
GH11-232	2011	PLP	Monitoring/Study	156	2011	642391	1417673.69	2161848.35	S0035035W13	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39			Stable
GH11-233	2011	PLP	Monitoring/Study	149	2011	5												

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
GH11-2655	2011	PLP	Monitoring/Study	174.5	2012	540399	1405929.25	2157754.28	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
GH11-2665	2011	PLP	Monitoring/Study	72.5	2012	516819	1404645.25	2157410.29	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	52		Stable	
GH11-2675	2011	PLP	Monitoring/Study	60.5	2011	540430	1406973.97	2159159.61	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	56		Stable	
GH11-2685	2011	PLP	Monitoring/Study	95.5	2011	540436	1407143.03	2160231.33	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48		Stable	
GH11-2695	2011	PLP	Monitoring/Study	52.5	2011	516819	1404393.51	2158415.98	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	47		Stable	
GH11-2705	2011	PLP	Monitoring/Study	44.5	2011	540425	1407815.98	2157426.13	S0035035W22	9/17/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument	37		Stable	
GH11-2715	2011	PLP	Monitoring/Study	79.5	2011	524699	1407838.07	2155332.96	S0035035W27	10/3/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31		Stable	
GH11-2725	2011	PLP	Monitoring/Study	72.5	2011	524714	1408979.11	2156588.16	S0035035W23	9/17/2017	1-D	Wood Post	8-ft Snow Pole	Steel casing/Monument	48		Stable	
GH11-2735	2011	PLP	Monitoring/Study	27	2011	540426	1409846.34	2158323.9	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	52.32		Stable	
GH11-274	2011	PLP	Monitoring/Study	179	2012	516830	1403782.86	2162422.76	S0035035W15	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	24.6		Stable	
GH11-2755	2011	PLP	Monitoring/Study	154.5	2011	6423654	1408956.78	2154788.75	S0035035W26	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	21.96		Stable	
GH11-2765	2011	PLP	Monitoring/Study	123.5	2011	524685	1408260.88	2153970.96	S0035035W27	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.36		Stable	
GH11-277	2011	PLP	Monitoring/Study	297	2011	524840	1398102.38	2163202.99	S0035035W17	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.04		Stable	
GH11-2785	2011	PLP	Monitoring/Study	41	2011	516827	1404007.64	2160800.9	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	66		Stable	
GH11-2795	2011	PLP	Monitoring/Study	47.5	2011	540402	1405183.64	2161741.71	S0035035W15	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	54.12		Stable	
GH11-2805	2011	PLP	Monitoring/Study	72.5	2011	540442	1406861.43	2161539.39	S0035035W15	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.56		Stable	
GH11-281	2011	PLP	Monitoring/Study	169	2011	524840	1397395.92	2162779.3	S0035035W17	8/7/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH11-2825	2011	PLP	Monitoring/Study	58	2011	540443	1408176.54	2161594.5	S0035035W15	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.56		Stable	
GH11-2835	2011	PLP	Monitoring/Study	60	2011	540445	1410530.54	2161144.05	S0035035W14	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	51.48		Stable	
GH11-2845	2011	PLP	Monitoring/Study	35.5	2011	540438	1410034.7	2159944.02	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.88		Stable	
GH11-2855	2011	PLP	Monitoring/Study	33.8	2012	540427	1410797.18	2157427.91	S0035035W23	8/8/2013	1-E	Casing	8-ft Snow Pole	Steel Casing	60		Stable	
GH11-2865	2011	PLP	Monitoring/Study	37	2011	524715	1410513.81	2156133.15	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	51.84		Stable	
GH11-287	2011	PLP	Monitoring/Study	244	2011	524837	1398645.72	2161590.67	S0035035W16	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.84		Stable	
GH11-2885	2011	PLP	Monitoring/Study	113	2011	524685	1407556.27	2153451.26	S0035035W27	8/9/2013	1-E	Casing	8-ft Snow Pole	Steel Casing	40.44		Stable	
GH11-2895	2011	PLP	Monitoring/Study	40	2011	540431	1408356.45	2159183.12	S0035035W22	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.2		Stable	
GH11-2905	2011	PLP	Monitoring/Study	50	2011	540429	1413761.08	2158002.88	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	54		Stable	
GH11-2915	2011	PLP	Monitoring/Study	40	2011	540432	1409946.31	2159262.16	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	27.12		Stable	
GH11-2925	2011	PLP	Monitoring/Study	160	2011	524715	1411192.08	2155769.41	S0035035W23	10/3/2017	1-E	Casing	8-ft Snow Pole	Steel casing/Monument	6		Stable	
GH11-293	2011	PLP	Monitoring/Study	229	2011	524833	1397745.38	2161224.96	S0035035W20	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	18.24		Stable	
GH11-294	2011	PLP	Monitoring/Study	224	2011	524834	1398668.72	2160964.45	S0035035W21	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	52		Stable	
GH11-2955	2011	PLP	Monitoring/Study	50	2011	524716	1412154.55	2156425.71	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.68		Stable	
GH11-296	2011	PLP	Monitoring/Study	239	2011	524834	1399428.34	2160999.24	S0035035W21	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH12-297	2012	PLP	Monitoring/Study	206.75	2012	524786	1404578.759	2140140.591	S0045035W03	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30.36		Stable	
GH12-298	2012	PLP	Monitoring/Study	254	2012	524783	1404903.763	2138956.624	S0045035W10	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.76		Stable	
GH12-299	2012	PLP	Monitoring/Study	109	2012	642391	1417972.652	2162723.98	S0035035W13	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	27.36		Stable	
GH12-300	2012	PLP	Monitoring/Study	104	2012	642390	1415080.4	2163415.031	S0035035W13	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42.84		Stable	
GH12-3015	2012	PLP	Monitoring/Study	237	2012	516963	1402778.347	2140560.055	S0045035W04	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.8		Stable	
GH12-302	2012	PLP	Monitoring/Study	259.5	2012	642382	1414515.835	2158595.711	S0035035W24	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	29.4		Stable	
GH12-303	2012	PLP	Monitoring/Study	140	2012	642390	1415002.847	2162586.726	S0035035W13	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.32		Stable	
GH12-3045	2012	PLP	Monitoring/Study	379.4	2013	524781	1402270.088	2139773.081	S0045035W09	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.6		Stable	
GH12-305	2012	PLP	Monitoring/Study	110	2013	540446	1412260.959	2162097.482	S0035035W14	8/11/2013	1-E	Casing	8-ft Snow Pole	Steel Casing	72		Stable	
GH12-306	2012	PLP	Monitoring/Study	110	2013	540457	1410424.473	2163762.847	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	24		Stable	
GH12-307	2012	PLP	Monitoring/Study	160	2012	540449	1408472.4	2163467.9	S0035035W15	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.72		Stable	
GH12-308	2012	PLP	Monitoring/Study	175	2012	540403	1405659.653	2163626.107	S0035035W15	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	18.36		Stable	
GH12-309	2012	PLP	Monitoring/Study	135	2012	516833	1404158.162	2163209.533	S0035035W15	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	28.8		Stable	
GH12-310	2012	PLP	Monitoring/Study	270	2012	531447	1393891.447	2160357.899	S0035035W20	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH12-3115	2012	PLP	Monitoring/Study	254	2013	516963	1402866.308	2141130.684	S0045035W04	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	55.08		Stable	
GH12-312	2012	PLP	Monitoring/Study	110	2012	646605	1389908.31	2163184.814	S0035035W18	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43.92		Stable	
GH12-3135	2012	PLP	Monitoring/Study	128	2013	516809	1400245.75	2157018.398	S0035035W21	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35		Stable	
GH12-314	2012	PLP	Monitoring/Study	110	2012	531449	1390587.619	2162597.956	S0035035W18	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.68		Stable	
GH12-3155	2012	PLP	Monitoring/Study	159	2013	516809	1400205.26	2156971.758	S0035035W21	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39		Stable	
GH12-316	2012	PLP	Monitoring/Study	155	2012	531451	1394025.102	2161663.922	S0035035W17	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.16		Stable	
GH12-3175	2012	PLP	Monitoring/Study	73	2012	516821	1401712.77	2158844.94	S0035035W21	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43		Stable	
GH12-318	2012	PLP	Monitoring/Study	200	2012	524832	1396770.475	2160760.97	S0035035W20	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.72		Stable	
GH12-3195	2012	PLP	Monitoring/Study	74.5	2012	516811	1402439.303	2157155.684	S0035035W21	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
GH12-3205	2012	PLP	Monitoring/Study	34	2012	516874	1402815.393	2155055.679	S0035035W28	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43		Stable	
GH12-3215	2012	PLP	Monitoring/Study	119	2012	524825	1405524.763	2154102.606	S0035035W27	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44		Stable	
GH12-3225	2012	PLP	Monitoring/Study	161.5	2012	540399	1405795.647	2157380.119	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45		Stable	
GH12-3235	2012	PLP	Monitoring/Study	39	2012	540426	1409001.977	2157995.529	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.24		Stable	
GH12-3245	2012	PLP	Monitoring/Study	259	2012	642364	1410545.822	2155080.123	S0035035W26	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.36		Stable	
GH12-325	2012	PLP	Monitoring/Study	165	2012	516815	1398837.103	2158346.016	S0035035W21	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument/Water Valve	32		Stable	
GH12-326	2012	PLP	Monitoring/Study	350	2013	516860	1399545.342	2152675.312	S0035035W28	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43.32		Stable	
GH12-3275	2012	PLP	Monitoring/Study	239	2012	642364	1410320.241	2155105.71	S0035035W26	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	61.44		Stable	
GH12-328	2012	PLP	Monitoring/Study	200	2013	516855	1401506.166	2150879.769	S0035035W28	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	29.04		Stable	
GH12-3295	2012	PLP	Monitoring/Study	102	2013	524823	1404078.306	2152777.48	S0035035W27	7/30/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap	41.4		Stable	
GH12-3305</																		

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
GH13-361	2013	PLP	Monitoring/Study	160	2013	642443	1379524	2161793	S0035036W14	8/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-362	2013	PLP	Monitoring/Study	160	2013	642440	1380374.342	2161108.255	S0035036W23	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	24		Stable	
GH13-363	2013	PLP	Monitoring/Study	185	2013	642443	1378140	2162880	S0035036W14	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	24		Stable	
GH13-364	2013	PLP	Monitoring/Study	155	2013	642442	1376441.446	2162678.304	S0035036W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-365	2013	PLP	Monitoring/Study	120	2013	642442	1374769.337	2162544.213	S0035036W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-366	2013	PLP	Monitoring/Study	215	2013	642441	1374194.24	2161892.322	S0035036W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-367	2013	PLP	Monitoring/Study	125	2013	642437	1373720.14	2160780.208	S0035036W22	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-368	2013	PLP	Monitoring/Study	110	2013	642437	1372863.992	2159550.217	S0035036W22	8/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-369	2013	PLP	Monitoring/Study	220	2013	642440	1381084.757	2161085.651	S0035036W23	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-370	2013	PLP	Monitoring/Study	205	2013	642440	1381385.441	2161291.296	S0035036W23	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-371	2013	PLP	Monitoring/Study	285	2013	642440	1381818.851	2160979.871	S0035036W23	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-372	2013	PLP	Monitoring/Study	300	2013	566973	1382581.793	2160549.656	S0035036W24	5/17/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	30		Stable	
GH13-373	2013	PLP	Monitoring/Study	225	2013	566970	1383962.842	2159874.228	S0035036W24	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-374	2013	PLP	Monitoring/Study	135	2013	566971	1385250.602	2158935.488	S0035036W24	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-375	2013	PLP	Monitoring/Study	145	2013	566967	1385795.403	2158367.576	S0035036W24	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-376	2013	PLP	Monitoring/Study	310	2013	642418	1373311.88	2149136.636	S0035036W34	8/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-377	2013	PLP	Monitoring/Study	240	2013	642418	1372066.226	2149333.486	S0035036W34	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	24		Stable	
GH13-378	2013	PLP	Monitoring/Study	305	2013	642417	1371290.144	2149535.457	S0035036W33	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-379	2013	PLP	Monitoring/Study	215	2013	642417	1369837.103	2149720.201	S0035036W33	8/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-380	2013	PLP	Monitoring/Study	345	2013	642415	1375482.005	2148487.89	S0035036W34	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-381	2013	PLP	Monitoring/Study	300	2013	642418	1374200.093	2149147.486	S0035036W34	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap	30		Stable	
GH13-382	2013	PLP	Monitoring/Study	420	2013	642414	1372932.127	2148390.985	S0035036W34	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-383	2013	PLP	Monitoring/Study	250	2013	642414	1372990.717	2146586.706	S0035036W34	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
GH13-384	2013	PLP	Monitoring/Study	160	2013	642446	1382564.6	2165098.513	S0035036W14	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-385	2013	PLP	Monitoring/Study	145	2013	566985	1383048.288	2165360.259	S0035036W13	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
GH13-386	2013	PLP	Monitoring/Study	165	2013	566985	1383566.54	2165041.486	S0035036W13	9/30/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
KP-P4	2004	NDM	Monitoring/Study	54	2004	524698	1406223.045	2155591.009	S0035035W27	5/17/2017	3-E	Wood Post				Grouted and Plugged [7]		
MW-04-01D	2004	NDM	Monitoring/Study	135.12	2004	638785	1378224.506	2124912.641	S0045036W23	9/15/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	31.56		Stable	Reclassified as active site
MW-04-01M	2004	NDM	Monitoring/Study	70.65	2004	638785	1378236.685	2124906.169	S0045036W23	9/15/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	22.8		Stable	Reclassified as active site
MW-04-01S	2004	NDM	Monitoring/Study	16.69	2004	638785	1378206.184	2124920.496	S0045036W23	9/15/2017	3-E					Grouted and Plugged [7]		Casing removed
MW-04-02D	2004	NDM	Monitoring/Study	147	2005	643915	1399454.651	2121671.318	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39		Stable	
MW-04-02S	2004	NDM	Monitoring/Study	101	2005	643915	1399459.36	2121655.204	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.56		Stable	
MW-04-03D	2004	NDM	Monitoring/Study	195.57	2005	516949	1400176.348	2136063.554	S0045035W09	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.24		Stable	
MW-04-04	2004	NDM	Monitoring/Study	25	2004	540424	1400176.348	2158182.566	S0035035W22	5/17/2017	1-E	Wood Post	8-ft Snow Pole	Steel Casing/Water Valve	18		Stable	
MW-04-05D	2004	NDM	Monitoring/Study	105.73	2004	516850	1403272.445	2149287.525	S0035035W33	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.8		Stable	
MW-04-05M	2004	NDM	Monitoring/Study	67.38	2004	516850	1403291.406	2149285.041	S0035035W33	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	51.48		Stable	
MW-04-05S	2004	NDM	Monitoring/Study	43.49	2004	516850	1403286.201	2149303.569	S0035035W33	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.6		Stable	
MW-04-06D	2004	NDM	Monitoring/Study	95.8	2004	642448	1382243.203	2168254.358	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.8		Stable	
MW-04-07D	2004	NDM	Monitoring/Study	75.15	2004	642418	1373316.039	2150205.354	S0035036W34	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	52.08		Stable	
MW-04-07S	2004	NDM	Monitoring/Study	34.35	2004	642418	1373295.911	2150210.528	S0035036W34	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	52.2		Stable	
MW-04-08D	2004	NDM	Monitoring/Study	100.37	2005	567050	1400005.758	2172701.569	S0035035W04	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	49.8		Stable	
MW-04-08M	2004	NDM	Monitoring/Study	48.82	2005	567050	1399992.889	2172688.012	S0035035W04	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.6		Stable	
MW-04-08S	2004	NDM	Monitoring/Study	21.84	2005	567050	1399989.463	2172705.458	S0035035W04	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	57.96		Stable	
MW-04-09D	2004	NDM	Monitoring/Study	81.45	2004	642418	1373501.33	2150021.845	S0035036W34	9/15/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap	32.88		Stable	
MW-04-10	2004	NDM	Monitoring/Study	44	2004	566985	1382987.693	2165426.137	S0035036W13	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.88		Stable	
MW-04-11D	2004	NDM	Monitoring/Study	136	2004	643921	1398334.396	2126318.899	S0045035W21	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	56.76		Stable	
MW-04-11M	2004	NDM	Monitoring/Study	112	2004	643921	1398337.707	2126303.57	S0045035W21	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	49.44		Stable	
MW-04-11S	2004	NDM	Monitoring/Study	71	2004	643921	1398343.45	2126290.58	S0045035W21	9/15/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.92		Stable	
MW-05-02M	2005	NDM	Monitoring/Study	63.1	2005	643915	1399436.503	2121667.139	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	33.6		Stable	
MW-05-02SR	2005	NDM	Monitoring/Study	18.5	2005	643915	1399444.077	2121654.214	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	50.64		Stable	
MW-05-11SS	2005	NDM	Monitoring/Study	33	2005	643921	1398356.433	2126298.225	S0045035W21	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.4		Stable	
MW-05-12D	2005	NDM	Monitoring/Study	129	2005	516871	1399175.088	2155571.378	S0035035W28	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
MW-05-12S	2005	NDM	Monitoring/Study	45.5	2005	516871	1399194.961	2155584.734	S0035035W28	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	50		Stable	
MW-05-13D	2005	NDM	Monitoring/Study	112	2005	638785	1376781.553	2127182.091	S0045036W23	10/3/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.92		Stable	
MW-05-13S	2005	NDM	Monitoring/Study	33	2005	638785	1376799.201	2127166.901	S0045036W23	10/3/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.64		Stable	
MW-05-14D	2005	NDM	Monitoring/Study	110	2005	524755	1405519.742	2131539.53	S0045035W15	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.08		Stable	
MW-05-14S	2005	NDM	Monitoring/Study	53	2005	524755	1405502.676	2131549.776	S0045035W15	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.4		Stable	
P-04-01/St	2004	NDM	Monitoring/Study	44	2004	516867	1401319.018	2154315.713	S0035035W28	5/17/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	36		Stable	
P-04-02D	2004	NDM	Monitoring/Study	86	2004	516868	1402465.918	2154026.134	S0035035W28	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
P-04-02M	2004	NDM	Monitoring/Study	70.31	2004	516868	1402463.549	2154047.785	S0035035W28	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
P-04-03	2004	NDM	Monitoring/Study	24.5	2004	516874	1403273.49	2154762.759	S0035035W28	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	0		Stable	
P-04-04AD	2004	NDM	Monitoring/Study	93.85	2004	524827	1405203.45	2155653.938	S0035035W27	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
P-04-04AS	2004	NDM	Monitoring/Study	59	2004	524827	1405220.928	2155638.388	S0035035W27	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
P-04-04M	2004	NDM	Monitoring/Study	58.24	2005	524827	1405026.992	2155079.185	S0035035W27	9/16/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	40		Stable	Reclassified as active site
P-04-06D	2004	NDM	Monitoring/Study	116.4	2004	524828	1405472.605	2155849.914	S0035035W22	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32	</		

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
P-05-22D	2005	NDM	Monitoring/Study	237	2005	516968	1402868.99	2142370.316	S0045035W04	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	21.84		Stable	
P-05-23	2005	NDM	Monitoring/Study	62.5	2005	566820	1399576.28	2131333.679	S0045035W16	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	28.44		Stable	
P-05-24D	2005	NDM	Monitoring/Study	142	2005	566753	1403034.713	2128064.528	S0045035W22	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.2		Stable	
P-05-24S	2005	NDM	Monitoring/Study	28.5	2005	566753	1403044.255	2128088.403	S0045035W22	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.96		Stable	
P-05-25	2005	NDM	Monitoring/Study	62	2005	524755	1405574.998	2131539.797	S0045035W15	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	33.6		Stable	
P-05-26D	2005	NDM	Monitoring/Study	180	2005	516949	1399727.704	2135000.27	S0045035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	47.64		Stable	
P-05-26M	2005	NDM	Monitoring/Study	102.6	2005	516949	1399709.489	2135007.319	S0045035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	53.88		Stable	
P-05-26S	2005	NDM	Monitoring/Study	30	2005	516949	1399727.361	2134985.617	S0045035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.4		Stable	
P-05-27D	2005	NDM	Monitoring/Study	148	2005	643915	1399813.15	2123737.524	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	16.8		Stable	
P-05-27M	2005	NDM	Monitoring/Study	75	2005	643915	1399827.248	2123723.992	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	38.64		Stable	
P-05-27S	2005	NDM	Monitoring/Study	38	2005	643915	1399814.121	2123723.367	S0045035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.04		Stable	
P-05-28D	2005	NDM	Monitoring/Study	1	2005	642364	1410045.644	2153654.343	S0035035W26	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.76		Stable	
P-05-28S	2005	NDM	Monitoring/Study	1	2005	642364	1410031.087	2153664.219	S0035035W26	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.76		Stable	
P-05-29D	2005	NDM	Monitoring/Study	124.3	2005	524698	1406633.255	2154703.505	S0035035W27	10/6/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41		Stable	
P-05-29D2	2005	NDM	Monitoring/Study	1	2005	524698	1406661.953	2154696.955	S0035035W27	10/6/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	38		Stable	
P-05-29M	2005	NDM	Monitoring/Study	60	2005	524698	1406676.329	2154712.637	S0035035W27	10/6/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
P-05-29S	2005	NDM	Monitoring/Study	28	2005	524698	1406637.934	2154722.007	S0035035W27	10/6/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41		Stable	
P-05-30D	2005	NDM	Monitoring/Study	115	2005	540442	1406447.867	2161592.285	S0035035W15	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.36		Stable	
P-05-30S	2005	NDM	Monitoring/Study	73	2005	540442	1406457.761	2161605.45	S0035035W15	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.56		Stable	
P-05-31D	2005	NDM	Monitoring/Study	156	2005	540437	1408340.935	2160140.699	S0035035W22	7/22/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
P-05-31S	2005	NDM	Monitoring/Study	28	2005	540437	1408354.572	2160159.474	S0035035W22	7/22/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
P-05-32D	2005	NDM	Monitoring/Study	101	2005	540432	1409690.176	2159073.689	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.56		Stable	
P-05-33D	2005	NDM	Monitoring/Study	65	2005	540433	1411247.206	2159456.169	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	21.48		Stable	
P-05-34D	2005	NDM	Monitoring/Study	95	2005	540438	1409830.088	2160495.483	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.2		Stable	
P-05-35	2005	NDM	Monitoring/Study	75	2005	540449	1407881.045	2162627.556	S0035035W15	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.88		Stable	
P-05-36D	2005	NDM	Monitoring/Study	151	2005	524828	1405755.413	2157046.462	S0035035W22	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.64		Stable	
P-05-36M	2005	NDM	Monitoring/Study	90.8	2005	524828	1405763.539	2157031.92	S0035035W22	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45		Stable	
P-05-36S	2005	NDM	Monitoring/Study	34	2005	524828	1405746.046	2157061.145	S0035035W22	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	46		Stable	
P-06-37D	2006	NDM	Monitoring/Study	200	2006	540450	1409444.728	2163539.612	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.24		Stable	
P-06-37DA	2006	NDM	Monitoring/Study	205	2006	540450	1409444.728	2163539.612	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.24		Stable	
P-06-37M	2006	NDM	Monitoring/Study	140	2006	540450	1409436.563	2163523.675	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.12		Stable	
P-06-37S	2006	NDM	Monitoring/Study	29	2006	540450	1409432.049	2163507.877	S0035035W14	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.84		Stable	
P-06-38D	2006	NDM	Monitoring/Study	200	2006	540466	1406579.039	2166679.941	S0035035W10	9/16/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument	41.64		Stable	
P-06-38M	2006	NDM	Monitoring/Study	200	2006	540466	1406562.607	2166690.207	S0035035W10	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.24		Stable	
P-06-39D	2006	NDM	Monitoring/Study	70	2006	540440	1412117.714	2160790.847	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	46.92		Stable	
P-06-39S	2006	NDM	Monitoring/Study	35	2006	540440	1412125.791	2160809.261	S0035035W23	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.28		Stable	
P-06-40D	2006	NDM	Monitoring/Study	145	2006	540435	1412908.677	2158570.646	S0035035W23	9/17/2017	1-D	Casing	8-ft Snow Pole	Steel casing/Plug or Cap	34.92		Stable	
P-06-40M	2006	NDM	Monitoring/Study	63	2006	540435	1412942.608	2158592.458	S0035035W23	9/17/2017	1-D	Casing	8-ft Snow Pole	Steel casing/Plug or Cap	30		Stable	Reclassified as active site
P-06-40S	2006	NDM	Monitoring/Study	20	2006	540435	1412926.867	2158584.15	S0035035W23	9/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument/Plug or Cap	34.2		Stable	
P-06-41D	2006	NDM	Monitoring/Study	200	2006	642392	1420118.746	2160960.167	S0035034W18	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.52		Stable	
P-06-41M	2006	NDM	Monitoring/Study	63	2006	642392	1420135.843	2160970.204	S0035034W18	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	33.96		Stable	
P-06-41S	2006	NDM	Monitoring/Study	41.5	2006	642392	1420151.349	2160981.771	S0035034W18	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.8		Stable	
P-07-42D	2007	PLP	Monitoring/Study	126	2007	567053	1404364.327	2171816.719	S0035035W03	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.8		Stable	
P-07-42S	2007	PLP	Monitoring/Study	52	2007	567053	1404365.567	2171794.518	S0035035W03	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.52		Stable	
P-07-43D	2007	PLP	Monitoring/Study	133	2007	568256	1408690.585	2171789.537	S0035035W03	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.16		Stable	
P-07-43M	2007	PLP	Monitoring/Study	72	2007	568256	1408707.058	2171782.696	S0035035W03	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30.6		Stable	
P-07-43S	2007	PLP	Monitoring/Study	32	2007	568256	1408702.209	2171767.38	S0035035W03	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42.48		Stable	
P-07-44D	2007	PLP	Monitoring/Study	89	2007	644251	1411817.508	2174231.55	S0035035W02	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
P-07-44S	2007	PLP	Monitoring/Study	27	2007	644251	1411808.679	2174241.26	S0035035W02	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42.6		Stable	
P-07-45D	2007	PLP	Monitoring/Study	60	2007	644236	1418783.246	2169419.931	S0035035W12	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.64		Stable	
P-07-46D	2007	PLP	Monitoring/Study	52.5	2007	642399	1419004.113	2163585.76	S0035035W13	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45		Stable	
P-07-47D	2007	PLP	Monitoring/Study	80	2007	642383	1418172.063	2158452.207	S0035035W24	8/8/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	31.2		Stable	
P-07-48D	2007	PLP	Monitoring/Study	62	2007	643935	1380043.655	2172840.5	S0035036W02	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43.56		Stable	
P-07-48S	2007	PLP	Monitoring/Study	32.5	2007	643935	1380030.269	2172824.883	S0035036W02	8/11/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	54.48		Stable	
P-07-49D	2007	PLP	Monitoring/Study	100	2007	566998	1384395.833	2167007.009	S0035036W12	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	47.28		Stable	
P-07-49S	2007	PLP	Monitoring/Study	22	2007	566998	1384409.83	2167025.051	S0035036W12	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42.36		Stable	
P-07-50D	2007	PLP	Monitoring/Study	161	2008	642449	1379659.906	2171914.671	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43.68		Stable	
P-07-50S	2007	PLP	Monitoring/Study	171.5	2008	642449	1379684.931	2171909.765	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	33.24		Stable	
P-07-50S5	2007	PLP	Monitoring/Study	116	2008	642449	1379684.33	2171931.263	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.08		Stable	
P-07-51D	2007	PLP	Monitoring/Study	85	2008	642441	1372610.235	2162374.689	S0035036W15	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.8		Stable	
P-07-51S	2007	PLP	Monitoring/Study	20	2008	642441	1372628.214	2162386.836	S0035036W15	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	51.72		Stable	
P-07-52D	2007	PLP	Monitoring/Study	60	2008	642420	1367488.205	2153681.514	S0035036W28	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	57.48		Stable	
P-07-52S	2007	PLP	Monitoring/Study	28	2008	642420	1367475.766	2153675.659	S0035036W28	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	49.68		Stable	
P-07-53D	2007	PLP	Monitoring/Study	161	2008	642449	1379645.904	2171900.255	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	30		Stable	
P-07-53S	2007	PLP	Monitoring/Study	82.5	2008	642449	1379652.456	2171885.882	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole</					

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes
P-08-69D	2008	PLP	Monitoring/Study	60	2008	642449	1379697.507	2170781.58	S0035036W11	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	49.08		Stable	
P-08-69S	2008	PLP	Monitoring/Study	19.8	2008	642449	1379734.461	2170789.731	S0035036W11	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	48.36		Stable	
P-08-70D	2008	PLP	Monitoring/Study	68.2	2008	642437	1372333.482	2159960.412	S0035036W22	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	46.8		Stable	
P-08-70S	2008	PLP	Monitoring/Study	19.8	2008	642437	1372325.961	2159988.269	S0035036W22	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	49.92		Stable	
P-08-71D	2008	PLP	Monitoring/Study	49	2008	566978	1384970.817	2161557.07	S0035036W13	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.96		Stable	
P-08-71S	2008	PLP	Monitoring/Study	10	2008	566978	1384944.9	2161558.797	S0035036W13	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.72		Stable	
P-08-72D	2008	PLP	Monitoring/Study	58.2	2009	566995	1388955.775	2166366.382	S0035035W18	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.52		Stable	
P-08-72S	2008	PLP	Monitoring/Study	15.3	2009	566995	1388916.982	2166379.664	S0035035W18	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	35.64		Stable	
P-08-73D	2008	PLP	Monitoring/Study	114	2008	531443	1393537.91	2158962.29	S0035035W20	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	0		Stable	
P-08-73S	2008	PLP	Monitoring/Study	44.7	2008	531443	1393498.8	2158977.529	S0035035W20	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.8		Stable	
P-08-74D	2008	PLP	Monitoring/Study	94.7	2008	531434	1392173.45	2156427.349	S0035035W19	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.68		Stable	
P-08-74S	2008	PLP	Monitoring/Study	51.4	2008	531434	1392204.367	2156469.398	S0035035W19	6/29/2017	1-E	Casing		Steel Casing	47.52		Stable	
P-08-75D	2008	PLP	Monitoring/Study	172.15	2009	540421	1403241.135	2170960.694	S0035035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.6		Stable	
P-08-75M	2008	PLP	Monitoring/Study	129.37	2009	540421	1403194.559	2170926.323	S0035035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36.24		Stable	
P-08-75S	2008	PLP	Monitoring/Study	41.4	2009	540421	1403218.72	2170945.397	S0035035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.16		Stable	
P-08-76D	2008	PLP	Monitoring/Study	138.05	2008	553016	1367182.783	2170553.058	S0035036W09	8/10/2013	1-E	Monument		Steel Casing/Monument	53.88		Stable	
P-08-76S	2008	PLP	Monitoring/Study	35.89	2008	553016	1367157.148	2170543.83	S0035036W09	8/10/2013	1-E	Monument		Steel Casing/Monument	53.64		Stable	
P-08-77D	2008	PLP	Monitoring/Study	93	2008	644483	1368319.331	2173790.5	S0035036W04	8/10/2013	1-E	Monument		Steel Casing/Monument	48.48		Stable	
P-08-77S	2008	PLP	Monitoring/Study	23.5	2008	644483	1368288.514	2173771.855	S0035036W04	8/10/2013	1-E	Monument		Steel Casing/Monument	42.84		Stable	
P-08-78D	2008	PLP	Monitoring/Study	92.5	2008	644476	1368928.88	2176072.892	S0035036W04	8/10/2013	1-E	Monument		Steel Casing/Monument	41.88		Stable	
P-08-78S	2008	PLP	Monitoring/Study	32	2008	644476	1368943.329	2176036.441	S0035036W04	8/10/2013	1-E	Monument		Steel Casing/Monument	44.76		Stable	
P-08-79D	2008	PLP	Monitoring/Study	150.7	2009	552999	1361307.409	2166413.716	S0035036W18	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.56		Stable	
P-08-79M	2008	PLP	Monitoring/Study	70	2009	552999	1361318.684	2166364.899	S0035036W18	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.84		Stable	
P-08-79S	2008	PLP	Monitoring/Study	16	2009	552999	1361321.098	2166390.78	S0035036W18	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.96		Stable	
P-08-80D	2008	PLP	Monitoring/Study	127.1	2009	552980	1355540.969	2154870.741	S0035037W25	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.72		Stable	
P-08-80M	2008	PLP	Monitoring/Study	62.7	2009	552980	1355511.744	2154890.282	S0035037W25	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	45.24		Stable	
P-08-80S	2008	PLP	Monitoring/Study	17	2009	552980	1355519.047	2154922.634	S0035037W25	6/29/2017	1-E	Monument		Steel Casing/Monument	47.64		Stable	
P-08-81D	2008	PLP	Monitoring/Study	55.3	2009	552940	1350987.168	2143388.252	S0045037W01	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.88		Stable	
P-08-81S	2008	PLP	Monitoring/Study	17.5	2009	552940	1350974.144	2143370.161	S0045037W01	9/10/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable	
P-08-82D	2008	PLP	Monitoring/Study	73	2008	566751	1400534.153	2127914.3	S0045035W21	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.4		Stable	
P-08-82M	2008	PLP	Monitoring/Study	50.2	2008	566751	1400514.683	2127893.532	S0045035W21	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	39.48		Stable	
P-08-82S	2008	PLP	Monitoring/Study	21	2008	566751	1400488.371	2127902.906	S0045035W21	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.56		Stable	
P-08-83D	2008	PLP	Monitoring/Study	189.7	2009	524751	1405004.059	2130236.062	S0045035W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	32.16		Stable	
P-08-83M	2008	PLP	Monitoring/Study	102	2009	524751	1405015.922	2130215.305	S0045035W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	38.28		Stable	
P-08-83S	2008	PLP	Monitoring/Study	42	2009	524751	1405035.92	2130195.046	S0045035W15	7/13/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	38.64		Stable	
P-08-84D	2008	PLP	Monitoring/Study	79.7	2009	640084	1378294.13	2130954.432	S0045036W14	8/9/2013	1-E	Monument		Steel Casing/Monument	41.4		Stable	
P-08-84S	2008	PLP	Monitoring/Study	32.8	2009	640084	1378275.854	2130998.738	S0045036W14	8/9/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	40.8		Stable	
P-08-85D	2008	PLP	Monitoring/Study	137.6	2008	642383	1417344.731	2159988.184	S0035035W24	9/16/2017	1-D	Casing	8-ft Snow Pole	Steel casing/Plug or Cap	13.68		Stable	
P-08-85S	2008	PLP	Monitoring/Study	32.4	2008	642383	1417393.499	2160019.41	S0035035W24	9/16/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	47.16		Stable	
P-08-86D	2008	PLP	Monitoring/Study	89.6	2009	567024	1391936.262	2169841.824	S0035035W07	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.16		Stable	
P-08-86S	2008	PLP	Monitoring/Study	47.6	2009	567024	1391946.96	2169864.639	S0035035W07	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	37.92		Stable	
P-08-87D	2008	PLP	Monitoring/Study	70.4	2009	567025	1393970.239	2169843.61	S0035035W08	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42.24		Stable	
P-08-87S	2008	PLP	Monitoring/Study	52.1	2009	567025	1393988.057	2169867.279	S0035035W08	5/17/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	44.16		Stable	
P-08-88D	2008	PLP	Monitoring/Study	106.2	2009	553521	1439761.983	2136887.077	S0045034W10	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	41.04		Stable	
P-08-88S	2008	PLP	Monitoring/Study	32	2009	553521	1439763.596	2136853.284	S0045034W10	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	43.68		Stable	
P-08-89D	2008	PLP	Monitoring/Study	244.6	2009	553522	1428724.455	2136845.392	S0045034W08	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.2		Stable	
P-08-89M	2008	PLP	Monitoring/Study	152.7	2009	553522	1428774.364	2136886.675	S0045034W08	6/29/2017	1-E	Monument		Steel Casing/Monument	40.92		Stable	
P-08-89S	2008	PLP	Monitoring/Study	86	2009	553522	1428782.754	2136857.174	S0045034W08	6/29/2017	1-E	Monument		Steel Casing/Monument	37.56		Stable	
PS08-01	2008	FMM	Exploration	667	[3]	552913	1392683.418	2096479.33	S0055036W24	9/15/2017	3-E					Closed [4]		Casing removed
PS08-02	2008	FMM	Exploration	310	[3]	642066	1357433.733	2105464.641	S0055037W11	7/25/2016	3-E					Closed [4]		
PS08-03	2008	FMM	Exploration	1090	[3]	642062	1366695.865	2104948.009	S0055036W07	7/25/2016	3-E					Closed [4]		
PS08-04	2008	FMM	Exploration	1110	[3]	552955	1349253.791	2147346.569	S0035037W35	7/25/2016	3-E					Closed [4]		
PS08-05	2008	FMM	Exploration	1100	[3]	552958	1341026.736	2148863.158	S0035037W34	7/25/2016	3-E					Closed [4]		
PS08-06	2008	FMM	Exploration	340	[3]	642066	1357443.575	2105464.79	S0055037W11	7/25/2016	3-E					Closed [4]		
PS08-07	2008	FMM	Exploration	833	[3]	642065	1361057.603	2104534.798	S0055037W11	7/25/2016	3-E					Closed [4]		
PW-04-01/01A	2004	NDM	Monitoring/Study	113.5	2004	524827	1405280.823	2155676.928	S0035035W27	10/5/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	36		Stable	
PW-04-03	2004	NDM	Monitoring/Study	115	2005	643921	1398353	2126314	S0045035W21	9/17/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	36		Stable	Reclassified as active site
PW-04-04	2004	NDM	Monitoring/Study	82.5	2005	638785	1378246.013	2124917.287	S0045036W23	8/4/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	36		Stable	Reclassified as active site
PW-05-05	2005	NDM	Monitoring/Study	110	2005	524755	1405519.421	2131565.578	S0045035W15	9/17/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	32		Stable	
PW-05-06	2005	NDM	Monitoring/Study	44.5	2005	524755	1405497.259	2131571.267	S0045035W15	9/17/2017	1-E	Casing	8-ft Snow Pole	Steel Casing	32		Stable	Reclassified as active site
PW-05-07/07A	2005	NDM	Monitoring/Study	177	2005	516949	1399713.731	2134992.203	S0035035W09	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	18		Stable	
PW-05-08	2005	NDM	Monitoring/Study	117	2005	524698	1406676.985	2154693.609	S0035035W27	10/6/2015	1-E	Casing	8-ft Snow Pole	Steel Casing	42		Stable	
PW-08-09	2008	PLP	Monitoring/Study	163	2008	642364	1410042.164	2153613.224	S0035035W26	9/17/2017	3-E					Grouted and Plugged [7]		Casing removed
PW-08-10	2008	PLP	Monitoring/Study	164.17	2008	642449	1379613.407	2171905.472	S0035036W11	8/10/2013	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	34.2		Stable	
Sill 01	1988	Cominco	Exploration	212	[1]	516779	1417178.115	2136440.295	S0045035W12	9/17/2017	3-E					Closed [4]		
Sill 02	1988	Cominco	Exploration	90	[1]	516779	1417178.02	2136440.064	S0045035W12	9/17/2017	3-E					Closed [4]		

Borehole ID	Drill Year	Operator	Borehole Purpose	Total Length (ft)	Reclamation Report Year	ADL File No	Northing (UTM NAD27)	Easting (UTM NAD27)	MTRS	Most Recent Inspection	Inspection Rating	Field Marker	Safety Markings	Surface Structures	Structure Height (in)	Closure Method	Soil/Vegetation	2017 Notes	
Sill 28	1989	Cominco	Exploration	242	[3]	516880	1418301.562	2140707.455	S004S035W01	8/20/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed	
Sill 29	1989	Cominco	Exploration	164	[3]	516880	1418299.778	2140825.571	S004S035W01	8/16/2016	3-E					Closed [4]	Stable		
Sill 30	1989	Cominco	Exploration	270	[3]	516880	1418468.447	2140739.511	S004S035W01	8/20/2017	3-E					Closed [4]	Stable	Casing removed	
Sill 31	1989	Cominco	Exploration	485	[3]	516880	1418501.207	2140743.288	S004S035W01	8/20/2017	3-E	Wood Post				Closed [4]	Stable	Casing removed	
Sill 32	1989	Cominco	Exploration	105	[3]	516880	1418499.671	2140844.999	S004S035W01	8/16/2016	3-E					Closed [4]	Stable		
Sill 33	1989	Cominco	Exploration	172	[3]	516880	1418701.298	2140749.592	S004S035W01	8/16/2016	3-E					Closed [4]	Stable		
Sill 34	1989	Cominco	Exploration	188	[3]	516880	1418881.842	2140529.16	S004S035W01	8/16/2016	3-E					Closed [4]	Stable		
Sill 35	1989	Cominco	Exploration	100	[3]	516880	1418881.842	2140529.16	S004S035W01	8/16/2016	3-E					Closed [4]	Stable		
Sill 36	1989	Cominco	Exploration	145	[3]	567957	1419044.444	2140410.191	S004S034W06	8/16/2016	3-E					Closed [4]	Stable		
Sill 37	1989	Cominco	Exploration	211	[3]	567957	1419044.444	2140410.191	S004S034W06	8/16/2016	3-E					Closed [4]	Stable		
Sill 38	1989	Cominco	Exploration	496	[3]	516789	1417386.714	2137323.939	S004S035W12	8/16/2016	3-E					Closed [4]	Stable		
Sill 39	1989	Cominco	Exploration	365	[3]	516789	1417396.597	2137323.628	S004S035W12	8/16/2016	3-E					Closed [4]	Stable		
SRK-1	NA	PLP	Duplicate; same borehole as 4225; exclude from any summary calculations																
SRK-2	NA	PLP	Duplicate; same borehole as 4251; exclude from any summary calculations																
SRK-2A	2004	NDM	Monitoring/Study	84	2004	542569	1406174.16	2159587.212	S003S035W22	10/1/2015	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable		
SRK-5D/KP-P3D	2004	NDM	Monitoring/Study	79	2004	516867	1401942.567	2154180.384	S003S035W28	7/30/2017	1-D	Monument	8-ft Snow Pole	Steel Casing/Monument	42		Stable		
SRK-5M/KP-P3M	2004	NDM	Monitoring/Study	53	2004	516867	1401951.863	2154192.385	S003S035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	24		Stable		
SRK-5S/KP-P3S	2004	NDM	Monitoring/Study	24	2004	516867	1401972.049	2154169.937	S003S035W28	6/29/2017	1-E	Monument	8-ft Snow Pole	Steel Casing/Monument	60		Stable		

Field Name	Description
<i>Rec No</i>	Database record number
<i>Borehole ID</i>	PLP borehole identifier
<i>Drill Year</i>	Year in which borehole initially drilled; some drill activities span multiple years due to seasonal shutdown.
<i>Operator</i>	Legal entity responsible for claim activities during drill year: Cominco; Northern Dynasty Minerals, Ltd. (NDM); Full Metal Minerals (FMM); Pebble Limited Partnership (PLP)
<i>Borehole Purpose</i>	Basis for drilling hole, or current use. Some exploration boreholes are re-purposed for monitoring or study.
<i>Total Length (ft)</i>	Linear feet from surface
<i>Reclamation Report Year</i>	Year in which reclamation of drill site was reported to DNR; does not apply to exploration activities prior to October 15, 1991
<i>ADL File No</i>	Claim number on file with ADNR
<i>Northing</i>	(UTM NAD27)
<i>Easting</i>	(UTM NAD27)
<i>MTRS</i>	Meridian, Township, Range, Section for each borehole location
<i>Most Recent Inspection</i>	Date on which most recent documented observation occurred; photos taken during most inspections
<i>Inspection Rating</i>	Alpha-numeric code describing the STATUS and CONDITION of drill site. See 'Inspection Codes' worksheet for detailed explanation.
<i>Field Marker</i>	Structure identifying drill site location by survey ID or borehole ID. Wood post installed at most drill sites following reclamation, usually within a few feet of the original borehole. Posts are not typically installed at monitoring wells, where the above ground structure (monument or casing) serves as the field marker.
<i>Safety Markings</i>	Safety markings installed at locations with surface structures greater than 10 inches above ground.
<i>Surface Structures</i>	Permanent or semi-permanent structures installed at drill site.
<i>Structure Height (in)</i>	Inches above ground, measured perpendicular
<i>Closure Method</i>	Included only for fully decommissioned and closed boreholes.
<i>Note</i>	Inspector's explanation of site conditions, repairs made, or future inspection and repair needs.

Note	Description
[1]	Borehole drilled by Cominco prior to adoption of Reclamation Statute (AS 27.19); reclamation reporting not required prior to 10/15/1991. Reclamation status is based on most recent field inspection, if available.
[2]	Borehole drilled by Cominco in 1992; reclamation records unavailable. Reclamation status is based on most recent field inspection, if available.
[3]	Borehole drilled by Full Metal Minerals in 2008; reclamation records unavailable. PLP subsequently inspected and reclaimed sites in 2010. Reclamation status is reported for most recent inspection, if available.
[4]	Closure records unavailable.
[5]	Drilling records indicate borehole lost in shallow overburden due to collapse or other impediment; grouting not required. Borehole backfilled with excess material. Subsequent inspections have verified site stability.
[6]	Individual borehole data unavailable. 1997 Reclamation Report notes that all boreholes were closed with a bentonite plug.
[7]	Closure method based on review of driller timesheets (2006-2013); drill reports; consumables inventories; and/or standard operating procedures in place at the time.
[8]	Site no longer part of active Pebble Project.

Borehole Status Codes

Code	Category	Description
1	Active	Primary designation for active monitoring wells (groundwater quality, geotechnical, etc.). Also used for some former exploration boreholes that are maintained as possible water sources. Active sites do not have material plugs (grout, cement, bentonite) but may be fitted with mechanical plugs or caps.
2	Inactive	Site is not currently used as monitoring/study location, but is preserved for potential future use (e.g., additional drilling, water source). Inactive sites maintain aboveground structures (casing, valves, caps).
3	Closed	Site is decommissioned and closed. Borehole has been plugged as appropriate. All surface structures removed, with possible exception of wood post indicating location and borehole ID.

Maintenance/Reclamation Status Codes

Code	Category	Description
A	Major Repairs	Site condition presents an identified environmental compliance or health & safety concern, or is at risk of progressing if not addressed as soon as possible. Significant repairs necessary, typically requiring advanced planning, technical staff and additional equipment. Coordination and approval from DNR or other agency may be required. <i>Examples: upwelling of discolored or voluminous water; discharge to surface water.</i>
B	Minor repairs	Site condition requires repairs or rehabilitation, but is stable and not at risk of deteriorating further. Work does not require technical staff but generally cannot be completed during routine maintenance trips or by one person. Advance approval from DNR or other agency is usually not required unless circumstances dictate. All repair activities summarized in annual report. <i>Examples: Margo plug replacement/installation; large area rehabilitation or revegetation efforts requiring soil amendments and reseeding.</i>
C	Routine Maintenance or Additional Investigation	Maintenance requirements are small or insignificant and generally the result of normal operation or exposure to elements. Repairs can be completed by staff during routine inspections and do not require specialized equipment or advance planning. Also used to identify sites where conditions cannot be confirmed, thus requiring additional inspection or involvement of higher level staff. <i>Examples: application of sealant around cap; water valve replacement; ponded surface water with unconfirmed source.</i>
D	Stable/Monitored	Site condition is stable and has been fully reclaimed, but with past maintenance issues or known to have higher maintenance needs. All structural equipment, if any, is in good condition. Minimum monitoring is generally more frequent than Category E sites. Also applies to sites that have recently been repaired but require more frequent inspection to verify repairs and reclamation efforts. <i>Examples: artesian sites; sites with recent, major repairs.</i>
E	Stable/No Action	Site condition is stable and has been fully reclaimed. All structural equipment, if any, is in good condition. No known issues. No history of upwellings, leaks, or staining. Located in area unlikely to cause concern (e.g., wetlands, artesian zone). Inspection frequency is lower than Category D sites.