



# Preliminary Trail Condition Assessment

Rex Trail - Map 1 of 3

Trail condition assessment data and winter photos were collected during a field inspection conducted by DNR staff on December 5 and 6, 2007.

Summer photos taken during field inspections conducted by DNR staff during September 2007. Photos are representative of conditions encountered and depicted locations are approximate.

See Map 4 for Rex Trail general land ownership.

Base Map: USGS Topo 63k  
Projection: Alaska Albers  
Datum: NAD 83  
Scale: 1:63,360  
Created on: Jan 11, 2008  
Created by: Steve Taylor

## Trail Condition

- Good Condition
- Fair Condition
- ◇ Degraded
- ◇ Very Degraded
- ◆ Extremely Degraded

## Other Map Features

- ==== Rex Trail
- ==== ADL 415819
- Native Allotment
- State Land Disposal

