WINTER TRAIL

SLED ROAD

TATLANIKA CREEK

Preliminary Trail Condition Assessment

Rex Trail - Map 2 of 3

Trail condition assessment data and winter photos were collected during a field inspection conducted by DNR staff on December 5 and 6, 2007.

Summer photos taken during field inspections conducted by DNR staff during September 2007. Photos are representative of conditions encountered and depicted locations are approximate.

See Map 4 for Rex Trail general land ownership.

Base Map: USGS Topo 63k
Projection: Alaska Albers
Datum: NAD 83
Scale: 1:63,360
Created on: Jan 11, 2008
Created by: Steve Taylor

3 Miles

Trail Condition

- Good Condition
- Fair Condition
- Degraded
- Very Degraded
- Extremely Degraded

Other Map Features

- Rex Trail
- ADL 415819
- Native Allotment
- State Land Disposal